

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: K Y S 0 9 9 0 0 0 3									
						Year-Month-Day: 2 0 2 3 - 0 7 - 1 8									
						EPA Permit # (or RA): K Y I 0 3 9 9									
						Page 1 Of 2									
Inspector(s): Carl E. Weller (lead), Carol Chen Start Time: 10:50 am End Time: 10:54 am															
Facility Contact Information	Facility Name: Logsdon Valley Oil Co., Inc.														
	Street Address: 105 Bedford Court														
	City: Horse Cave County: Hart State: KY Zip: 42749														
	Nature of Business: Oil and gas extraction														
	Facility Owner/Operator: Logsdon Valley Oil Co., Inc. Phone: 270-537-4288														
	Email: estinson@scrtc.com Spencer Walters scw106@gmail.com														
	Facility Contact (if different): Ellen Stinson, President Phone: 270-537-4288														
	O/O Mailing Address: 105 Bedford Court City: Horse Cave County: Hart State: KY Zip: 42749														
Well Data from File	Well Name & #: Lora Turner #5														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: 46605														
	Latitude (°N): 37.183883 Longitude (°W): -85.783024 Elevation (ft): _____														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: ☐ Other: _____														
	Total Depth (ft): _____ Inner Casing Size (in): _____ Tubing Size (in): _____ Packer Depth (ft): _____ Inj. Zone: ☐ Open Hole; ☐ perforated; Top(ft) _____ Bottom(ft): _____ Max. Injection Pressure (psig): _____														
Field Measurements and Observations	Latitude (°N): 37.18396 Longitude (°W): -85.78316 Elevation (ft): _____														
	EPA GPS ID: SX8123 Well Status (see table): TA If not Active, Reported Date Last Active: 9/13/2019														
	Nature of Injected Fluid(s) if any: _____														
	General Condition of the Well Site: _____														
	Notes & Comments (include discrepancies from database values): _____														
	White bucket placed over the top of the well. No gauges are present.														
	Injection and tank battery lines are disconnected. Tubing Gauge: N/A														
	Tank battery is corroded. A few feet downhill of Production Gauge: N/A														
	the injection well is an unconfined pit filled with Surface Gauge: N/A														
	oily fluids.														
See reverse for additional observations, comments and photo log															
UIC Inspector Carl E. Weller Name: _____								UIC Inspector Carol Chen Name: _____							
Signature: CARL WELLER (Affiliate)								Signature: CAROL CHEN							
Digitally signed by CARL WELLER (Affiliate) Date: 2023.08.29 17:59:57 -04'00'								Digitally signed by CAROL CHEN Date: 2023.08.22 12:17:38 -04'00'							
Version 2018-04-18															

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#: <table><tr><td>K</td><td>Y</td><td>S</td><td>0</td><td>9</td><td>9</td><td>0</td><td>0</td><td>0</td><td>3</td></tr><tr><td>2</td><td>0</td><td>2</td><td>3</td><td>–</td><td>0</td><td>7</td><td>–</td><td>1</td><td>8</td></tr></table>												K	Y	S	0	9	9	0	0	0	3	2	0	2	3	–	0	7	–	1	8
K	Y	S	0		9	9	0	0	0	3																										
2	0	2	3		–	0	7	–	1	8																										
Year-Month-Day: <table><tr><td>2</td><td>0</td><td>2</td><td>3</td><td>–</td><td>0</td><td>7</td><td>–</td><td>1</td><td>8</td></tr></table>												2	0	2	3	–	0	7	–	1	8															
2	0	2	3	–	0	7	–	1	8																											
EPA Permit # (or RA): <table><tr><td>K</td><td>Y</td><td>I</td><td>0</td><td>3</td><td>9</td><td>9</td></tr></table>												K	Y	I	0	3	9	9																		
K	Y	I	0	3	9	9																														
Page <table><tr><td>2</td></tr></table> Of <table><tr><td>2</td></tr></table>												2	2																							
2																																				
2																																				
Field Measurements and Observations (Cont.)	(Cont)	Lora Turner #5										EPA Permit No. KYI0399										State Permit No. 46605														
	Photo Log	Photographer: Carl E. Weller																EPA Camera ID: SX8123																		
		Photo ID: 213				Time: 10:51 am				Lat (°N): 37.18396				Long (°W): -85.78316																						
Description: injection well close-up																																				
Photo ID: 214				Time: 10:51 am				Lat (°N): 37.18395				Long (°W): -85.78320																								
Description: Injection well and unconfined pit																																				
Photo ID:																Time:				Lat (°N):				Long (°W):												
Description:																																				
Photo ID:																Time:				Lat (°N):				Long (°W):												
Description:																																				
Photo ID:																Time:				Lat (°N):				Long (°W):												
Description:																																				
Photo ID:																Time:				Lat (°N):				Long (°W):												
Description:																																				
UIC Inspector																UIC Inspector																				
Name: Carl E. Weller																Name: Carol Chen																				
Signature: CARL WELLER (Affiliate) Digitally signed by CARL WELLER (Affiliate) Date: 2023.08.29 18:00:47 -04'00'																Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2023.08.22 12:18:04 -04'00'																				
Version 2018-04-18																																				