

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	03/20/2024
EPA Region/Program Conducting Inspection:	U.S. EPA, Region 4 Air Enforcement Branch
Company Name:	No Limit Diesel Performance
Facility Name:	No Limit Diesel Performance
Facility Physical Location: (street address, building/unit #)	2805 46 th Ave W
(city, state, zip code)	Bradenton, FL 34207

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Aleeka Broner

Field Inspector Name

ALEEKA BRONER

Signature

Digitally signed by ALEEKA
BRONER
Date: 2024.05.17 10:34:56 -04'00'

Date

Todd Groendyke

Name of Approving
Official

Section Chief, SAES

Title

TODD GROENDYKE

Signature

Digitally signed by TODD
GROENDYKE
Date: 2024.05.17 11:48:28 -04'00'

Date

FACILITY INSPECTION WORKSHEET

General Inspection Information			
Facility Name:	No Limit Diesel Performance	Inspection Date	3/20/2024
Facility Address:	2805 46 th Ave W Bradenton, FL 34207	Arrival/Departure Time	1:45 p.m. EDT 3:29 p.m. EDT
		Inspection Number/ID:	3601643923-2024
Primary Facility Representative & Title:	Joshua Gilley, Owner	Inspector(s):	Aleeka Broner, Lorianny Rivera
Facility Contact Phone/Email:	941-348-9221 nolomitdieselperformance@gmail.com		
Time Inspector Presented Credentials:	1:51 p.m. EDT	Compliance Assistance Materials Provided to Facility:	Small Business Resources Information Sheet, OECA Enforcement Alert, and Exhaust System Repair Guidelines Fact Sheet
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No		
Photographer Name:	N/A	Photograph Range:	N/A
Additional Personnel Present:		Areas Discussed:	☒ CBI ☒ Equipment (OBD scanner, camera) ☐ Safety Requirements
Facility Summary:	No Limit Diesel Performance, located in Bradenton FL, is a diesel vehicle service shop.		

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☐	Sells aftermarket parts		
☒	Service shop	The facility performs diesel engine repair services on light-duty diesel vehicles and fleet vehicles. Additionally, the facility indicated they offer performance enhancements, including turbocharger upgrades.	Services 1-2 vehicles/week
☐	Fleet		
☐	Other:		

Clean Air Act Title II: Mobile Source Inspection

Personnel Interviewed			
Name	Title/Position	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Joshua Gilley	Owner	941-348-9221 nolomitdieselpower@gmail.com	Broner

Documents Requested			
Document(s)	Status		Notes/Comments
Service invoices from August 2023 to November 2023	☒ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	Inspectors reviewed hard copies of service invoices on-site.
Receipts for parts purchased by the facility from August 2023 to November 2023	☒ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	Inspectors reviewed hard copies of parts purchase receipts on-site.
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	

Vehicles Inspected/Observed				
VIN (last 4 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Data Obtained? (Yes/No)	Observations (e.g., Who Performed Apparent Tampering?)
N/A			No	Inspectors observed the exterior of vehicles but did not photograph any vehicles.