



Photographs for Green Acres Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 445 taken by **Privacy** on 8/22/2023.

The direction of the photo is Southeast.

Description:

Green Acres sign and gate. Closed and locked upon arrival.



Photo number 446 taken by **Privacy** on 8/22/2023.

The direction of the photo is South.

Description:

Overview of cell 4.





Photographs for Green Acres Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 447 taken by **Privacy** on 8/22/2023.

The direction of the photo is Southeast.

Description:

Overview of cell 4 with exposed sludge at the bottom.



Photo number 448 taken by **Privacy** on 8/22/2023.

The direction of the photo is East.

Description:

Overview of cell 5.





Photographs for Green Acres Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 449 taken by **Privacy** on 8/22/2023.

Description:

Animal burrows on south side of cell 4.



Photo number 450 taken by **Privacy** on 8/22/2023.

The direction of the photo is North.

Description:

Overview of Green Acres cells 1, 2 and 3 also referred to as the lower cells.





Photographs for Green Acres Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 451 taken by **Privacy** on 8/22/2023.

The direction of the photo is East.

Description:

Kent Addition lift station sign.



Photo number 452 taken by **Privacy** on 8/22/2023.

The direction of the photo is West.

Description:

Kent Addition lift station control panel.





Photographs for Green Acres Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 453 taken by **Privacy** on 8/22/2023.

Description:

Kent Addition wet well at capacity.



Photo number 454 taken by **Privacy** on 8/22/2023.

Description:

Eagle View lift station control panel.





Photographs for Green Acres Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 455 taken by Privacy on 8/22/2023.

Description:

Eagle View wet well. Full trash basket.

