





USEPA Field Photo Report. Photos by Stephanie Tougas

Project: Savage Way, Plaistow, NH



Location: 42.83719874303382, -71.08889616740476

Photos:



savageway_20241119_095045.jpg
November 19, 2024 9:50 AM


Description: Wetland crossing

Location ID: 6



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83537189967112, -71.09047116798106

Photos:



savageway_20241119_101005.jpg
November 19, 2024 10:10 AM


Description: Outlet from retention pond

Location ID: 17




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83506929926522, -71.09010837627875

Photos:



savageway_20241119_101408.jpg
November 19, 2024 10:14 AM


Description: Conveyance at low point

Location ID: 19




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83475945131234, -71.09004638393617

Photos:



savageway_20241119_101546.jpg
November 19, 2024 10:16 AM


Description: Facing direction of brook off property in conveyance

Location ID: 20




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83555736968496, -71.08984865704181

Photos:



savageway_20241119_101907.jpg
November 19, 2024 10:19 AM


Description: Standing in low point side of retention pond

Location ID: 21



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83713750927068, -71.08886263916368

Photos:



savageway_20241119_095108.jpg
November 19, 2024 9:51 AM


Description: By wetland

Location ID: 7



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83720288663178, -71.08879564354133

Photos:



savageway_20241119_095141.jpg
November 19, 2024 9:51 AM


Description: Other side wetland

Location ID: 8




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83726877639749, -71.08821164560622

Photos:



savageway_20241119_095357.jpg
November 19, 2024 9:54 AM


Description: Behind active home build

Location ID: 9



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83728761668846, -71.08805227972181

Photos:



savageway_20241119_095436.jpg
November 19, 2024 9:54 AM


Description: delineated wetland behind homes

Location ID: 10



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83719043768737, -71.08763232632171

Photos:



savageway_20241119_095715.jpg
November 19, 2024 9:57 AM


Description: Cleaning debris

Location ID: 11



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83704953494181, -71.08773007903632

Photos:



savageway_20241119_095758.jpg
November 19, 2024 9:58 AM


Description: Leach field

Location ID: 12



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83674894385428, -71.08840643487352

Photos:



savageway_20241119_095959.jpg
November 19, 2024 10:00 AM


Description: Complete homes

Location ID: 13




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83609211317199, -71.08898473523026

Photos:



savageway_20241119_100440.jpg
November 19, 2024 10:05 AM


Description: Wetland with fill permitted -NHDES

Location ID: 14



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83574201627002, -71.0896960765343

Photos:



savageway_20241119_100719.jpg
November 19, 2024 10:08 AM


Description: Infiltration pond with constructed berm

Location ID: 15




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83563338148423, -71.08993589738674

Photos:



savageway_20241119_100837.jpg
November 19, 2024 10:08 AM


Description: Swale into retention pond

Location ID: 16




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83503764698227, -71.09057263209485

Photos:



savageway_20241119_101158.jpg
November 19, 2024 10:12 AM


Description: Downslope

Location ID: 18



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83675461934876, -71.08959070754057

Photos:



savageway_20241119_102133.jpg
November 19, 2024 10:21 AM


Description: Seeded

Location ID: 22




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83666948050784, -71.08879846289604

Photos:



savageway_20241119_102450.jpg
November 19, 2024 10:25 AM


Description: SWPPP reports

Location ID: 23




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83667169724644, -71.0888024654766

Photos:



savageway_20241119_102637.jpg
November 19, 2024 10:26 AM

Description: 2023 inspections


Location ID: 24

ED_019088A_00020464-00019




Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83668108213434, -71.08879158675116

Photos:



savageway_20241119_102704.jpg
November 19, 2024 10:27 AM


Description: Inspection

Location ID: 25



Field Photo Report

Project: Savage Way, Plaistow, NH



Location: 42.83667858987096, -71.08877195562906

Photos:



savageway_20241119_102744.jpg
November 19, 2024 10:27 AM

Description: NH permit

Location ID: 26