

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/09/2025	Time	11:20
		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS5907000		
		API Well No			
		Lease Name	MASON		
		Well ID	1		
Location	NW 32 25N 06E	Status	Inactive	Well Type	Disposal
Latitude	36.605507	Longitude	-96.683142		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	07/24/2015	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 0
FLM Canister Pressure		Actual Pressure			Max Volume 55000
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Well OS5907000 was connected but not injecting at the time of the inspection. There was no well sign to identify the well or current operator. EPA records indicate Contango Resources, LLC as the owner of record but the inspector received information the well may have been sold or is in the process of transferring ownership. At the time of the inspection, the well was overdue for MIT.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.605507, -96.683142		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010635

Orientation: SSW

Date of Photo: 4/09/2025

Time of Photo: 11:27AM

Latitude: 36.605507

Longitude: -96.683142

Photographer: Matthew Allen

Description: This was well OS5907000 at the time of the inspection. The well was connected but not injecting.