

UNLOADING SLIP

Car No. UTRX 92119

On Spot No. _____

Material VL

From _____

Received _____

ANALYSIS

OK TO UNLOAD _____

UNLOAD INTO TANK 601

Weight

Tank Reading

Date 9-20-83

By RR

Allmond 42

DTH 000006363