

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	0	9	9	0	0	0	3
Year-Month-Day:					2	0	2	4	-	1	0	-	2	4	
EPA Permit # (or RA):					K	Y	I	0	3	9	9				
					Page	1	Of	2							
Inspector(s): Carol Chen (lead), Lonnie Dorn Start Time: 7:35 am															
End Time: 7:40 am															
Facility Contact Information	Facility Name: Logsdon Valley Oil Co., Inc.														
	Street Address: 105 Bedford Court														
	City: Horse Cave County: Hart State: KY Zip: 42749														
	Nature of Business: oil production														
	Facility Owner/Operator: Ms. Ellen Stinson, President Phone: 270-537-4288														
	Email: estinson@scrtc.com														
	Facility Contact (if different): Phone:														
	O/O Mailing Address: 105 Bedford Court														
City: Horse Cave County: Hart State: KY Zip: 42749															
Well Data from File	Well Name & #: LORA TURNER #5														
	Well Type (see table): Class II-R, Enhanced Oil Recovery (EOR) State Permit: 46605														
	Latitude (°N): 37.183947 Longitude (°W): -85.783132 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: surface 6 5/8"														
	Total Depth (ft): 638 Inner Casing Size (in): 4 1/2" Tubing Size (in): 2 3/8" Packer Depth (ft): 597														
Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):															
Field Measurements and Observations	Latitude (°N): 000 Longitude (°W): 000 Elevation (ft):														
	EPA GPS ID: SC8284 Well Status (see table): AC If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any: Produced Waters (PW)														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	Can hear the trickling sounds of produced waters, flowing under gravity pressure, for enhanced oil recovery. The annulus pressure gauge is damaged/illegible. The flexible green line from the tank battery carries produced waters to the white plastic tubing for injection. The metallic parts of the wellcap show corrosion.														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.12.10 17:23:32 -05'00'								Signature:							
Version 2018-04-18															

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#: K Y S 0 9 9 0 0 0 3											
Year-Month-Day: 2 0 2 4 - 1 0 - 2 4																
EPA Permit # (or RA): K Y I 0 3 9 9																
Page 2 Of 2																
Field Measurements and Observations (Cont.)	(Cont.)															
	LORA TURNER #5 Class II-R, Enhanced Oil Recovery (EOR)															
	Photo Log	Photographer: Carol Chen EPA Camera ID: SC8284														
Photo ID: DSCN1495 Time: 7:35 am Lat (°N): 000 Long (°W) 000																
Description: injection well and one storage tank is visible																
Photo ID: DSCN1496 Time: 7:35 am Lat (°N): 000 Long (°W) 000																
Description: injection well and group of tanks are visible																
Photo ID: DSCN1497 Time: 7:37 am Lat (°N): 000 Long (°W) 000																
Description: production well is nearby																
Photo ID: DSCN1498 Time: 7:37 am Lat (°N): 000 Long (°W) 000																
Description: gauge on the producer																
Photo ID: DSCN1499 Time: 7:38 am Lat (°N): 000 Long (°W) 000																
Description: backside of the producer																
Photo ID: DSCN1500 Time: 7:38 am Lat (°N): 000 Long (°W) 000																
Description: close-up of the pressure gauge																
UIC Inspector						UIC Inspector										
Name: _____						Name: Carol Chen										
Signature: _____						CAROL CHEN										
						Digitally signed by CAROL CHEN Date: 2024.12.10 17:24:00 -05'00'										
						Version 2018-04-18										