

INDUSTRIAL HYGIENE RESULTS

DATE: March 25, 1983.

PROJECT: Sample and identify insulation on T-1098, water tank, near the tower in the Esters area; the protective cover has fallen off part of the insulation.

DATE OF SAMPLES: 3-23-83

<u>SUMMARY:</u>	<u>DATE</u>	<u>SAMPLE FROM</u>	<u>IDENTITY</u>
	3-23-83	Shredded, loose insulation, T-1098	No asbestos noted
	3-23-83	Rigid insulation, T-1098	No asbestos noted

RECOMMENDATIONS: Share this information with Esters area personnel.

DISCUSSION: Part of the cover has fallen off the insulation on T-1098 located near the S-W corner of the Esters tower. We noticed the strong wind on 3-23-83 was blowing the loose insulation on to the concrete pad. Thinking it might contain asbestos, we sampled it for identification.

METHOD OF ANALYSIS: Chemical Microscopy

DATA AND REPORT BY: H. G. Kuntz/K. E. Williams

ANALYSIS BY: V. H. McCool

COPY TO: D. G. Beddow, M. W. Bosserman, A. A. Cospers, Jr.,
K. A. Hickman, J. B. Mickey, A. G. Olds, R. L.
Pitrolo, F. M. Plechaty.


K. E. Williams