

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/03/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Martineau Operating Company	
Facility Name:	JN Peterson Lease	
Facility Physical Location:	32.354157, -94.91677	
(city, state, zip code)	Kilgore, Texas 75662	
Mailing address:	4625 Greenville Ave., Ste. 205	
(city, state, zip code)	Dallas, Texas 75206	
County/Parish:	Rusk County	
Facility Phone Number	214-361-0855	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011255	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Martineau Operating Company oil and gas facility located near Kilgore, Texas on 03/03/2020 for an unannounced inspection. There were no representatives of Martineau Operating Company present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the JN Peterson lease. The facility has the state identification number: RRC No. 06990.

Section II - OBSERVATIONS

I observed a cut in the berm wall of the secondary containment and therefore there was no secondary containment measures in place. There was not a berm around the separator as well. Minor amount of brine damage around the battery.

Section III – AREAS OF CONCERN

There was no secondary containment at the tank battery and separator.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A