

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
1/22/01	4033	GC #3	9.9	Bottom 74/Rx	0	no	Found nothing cleaned next check	N/A	N/A	N/A
03:00	65									
1-22-01	4034	GC #5		TOP OF HM STRIPPER FEED TR.	0	NO	Found nothing cleaned next check	N/A	N/A	N/A
0300	1C	6	9.9							
1-23-01	4035	GC #1		Comp. shed, N+5		NO	Put ELS pulling Lines & shed down to clear leaks	1-23	TC	TC
0615	01	1, 2, 3, 4, 5	8.1	Unloading, N. shed +5 not unloading	10					
1-23-01	4036	GC #5	10	South, middle new comp shed	10	NO	Pulling down with ELS to clear readings	1-23	TC	TC
0620	DW	1, 2, 4, 5		new east unloading						
1-23-01	4037	GC #1								
1518	01	#2	9.8	Unloading station						
1-25-01	4038	3	10.0	Top 74/R	15	NO	Tighten flange at pressure gauge	1-23	C.B.	C.B.
1945	BM	2								

This sheet is to be filled out in the event of one (1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
1-22-01	4027	GC #1		Upper section of N. + S. unloading station, between of stage M. + S. unloading	0	-	Checking Chromatograph	1-22-01	MCS	
1-22-01	4028	GC #2	5.0	Top of D600	0	NO	Nothing Found			
2104	GN	9	5.3							
1-22-01	4029	GC #1	7.5 5.5 9.0	N. VCM Railcar unloading station	0	0	nothing found	1-22		BBR
2224	GN	2		BBR						
1-22-01	4030	GC #1	6.1	S. VCM Railcar unloading station	0	0	nothing found	1-22		BBR
2246	GN	5		BBR						
1-22-01	4031	GC #2	5.2	Large Rec. Sigs, upstairs Changing Ring seal Filtration valves Leaking through	100	yes 163630	Changed out Valves	1/23/01	Mar	BK
2325	GN	4								
1-22-01	4032	GC #2	10.0 9.1	Top of D600	0	NO	Nothing Found			
2333	GN	9								

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.

This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.