

**Well Inspection**  
**Osage DNR / Environmental Protection Agency**  
**1201 Elm Street, Suite 500**  
**Dallas, Texas 75270**

|                                                |                                                                                                                                                                                                                                                                                                                                        |                                                  |                       |                         |                                        |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|-----------------------|-------------------------|----------------------------------------|
| <b>Inspector</b>                               | Matthew Allen                                                                                                                                                                                                                                                                                                                          | <b>Inspection Date</b>                           | 03/24/2026            | <b>Time</b>             | 14:30                                  |
|                                                |                                                                                                                                                                                                                                                                                                                                        | <b>Operator Representative</b>                   | McCann Resources, Inc |                         |                                        |
| <b>Operator Info</b>                           | McCann Resources, Inc<br>1613 West 6th Street<br>Bartlesville, OK 740033404<br>Phone: 918-337-4747                                                                                                                                                                                                                                     | <b>Inventory ID</b>                              | OS2210000             |                         |                                        |
|                                                |                                                                                                                                                                                                                                                                                                                                        | <b>API Well No</b>                               |                       |                         |                                        |
|                                                |                                                                                                                                                                                                                                                                                                                                        | <b>Lease Name</b>                                | Parker                |                         |                                        |
|                                                |                                                                                                                                                                                                                                                                                                                                        | <b>Well ID</b>                                   | W-75                  |                         |                                        |
| <b>Location</b>                                | SW 15 27N 12E                                                                                                                                                                                                                                                                                                                          | <b>Status</b>                                    | Active                | <b>Well Type</b>        | Enhanced Recovery                      |
| <b>Latitude</b>                                | 36.816148                                                                                                                                                                                                                                                                                                                              | <b>Longitude</b>                                 | -96.004593            |                         |                                        |
| <b>Inspection Reason</b>                       | Requested By Compliance Staff                                                                                                                                                                                                                                                                                                          | <b>Responsible Company at Time of Inspection</b> | McCann Resources, Inc |                         |                                        |
| <b>Inspect No.</b>                             |                                                                                                                                                                                                                                                                                                                                        | <b>Date Last MIT</b>                             | 05/08/2018            | <b>Last Test Result</b> | Acceptable                             |
| <b>Casing</b>                                  | 4.5                                                                                                                                                                                                                                                                                                                                    | <b>Tubing</b>                                    |                       | <b>USDW</b>             | 278                                    |
| <b>Monitoring Device Elected</b>               | N                                                                                                                                                                                                                                                                                                                                      | <b>Tubings</b>                                   |                       | <b>Annulus</b>          |                                        |
| <b>Monitoring Device FLM Canister Pressure</b> |                                                                                                                                                                                                                                                                                                                                        | <b>Fittings</b>                                  | N                     | N                       | <b>Max Pressure</b> 210                |
| <b>Lease Status</b>                            | Active                                                                                                                                                                                                                                                                                                                                 | <b>Actual Pressure</b>                           |                       |                         | <b>Max Volume</b>                      |
| <b>Barrel Monitor Hooked Up?</b>               | N                                                                                                                                                                                                                                                                                                                                      | <b>Determined?</b>                               |                       |                         | <b>Max Inj Units</b> Barrels Per Month |
| <b>Barrel Fluid Level (%)</b>                  |                                                                                                                                                                                                                                                                                                                                        | <b>Static Fluid Level</b>                        |                       |                         |                                        |
| <b>Flowline Hooked Up?</b>                     | N                                                                                                                                                                                                                                                                                                                                      | <b>Determined?</b>                               |                       |                         |                                        |
| <b>Injecting</b>                               | N                                                                                                                                                                                                                                                                                                                                      | <b>Injection Rate (bpd)</b>                      |                       |                         |                                        |
| <b>Inspection Comments</b>                     | Well, OS2210000 was casing reduced to 1" which prevented observance of the fluid level with the EPA echometer at the time of the inspection. There was no valve on the well and the installed pressure gauge was not legible. The well was disconnected and not injecting. At the time of the inspection the well was overdue for MIT. |                                                  |                       |                         |                                        |
| <b>Inspector Signature</b>                     |                                                                                                                                                                                                                                                                                                                                        |                                                  |                       |                         |                                        |
| <b>Supervisor Signature</b>                    |                                                                                                                                                                                                                                                                                                                                        |                                                  |                       |                         |                                        |

## Appendix 1

### Photograph Log

1 Photo



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

### Photograph Log

Photo No. 1

|                                 |                      |                 |
|---------------------------------|----------------------|-----------------|
| Location: 36.816148, -96.004593 |                      |                 |
| City: Bartlesville              | County/Parish: Osage | State: Oklahoma |



**Photo File Name:** R0010833

**Orientation:** SSW

**Date of Photo:** 03/24/2026

**Time of Photo:** 2:31

**Latitude:** 36.816148

**Longitude:** -96.004593

**Photographer:** Matthew Allen

**Description:** This was well OS2210000 at the time of the inspection. At the time of the inspection, the well was disconnected and was not injecting. The well was overdue for MIT.