

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	03/02/2026	Time	16:45
		Operator Representative	Superior Oil And Gas, LLC		
Operator Info	Superior Oil And Gas, LLC 42516 Hwy 412 Ringwood, OK 73768 Phone: 580-554-5515	Inventory ID	OS6332000		
		API Well No			
		Lease Name	CLARMORE		
		Well ID	1A		
Location	SE 32 23N 08E	Status	Inactive	Well Type	Disposal
Latitude	36.420662	Longitude	-96.465689		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Superior Oil And Gas, LLC		
Inspect No.		Date Last MIT	07/17/2019	Last Test Result	Acceptable
Casing	5.5	Tubing	2.375	USDW	560
Monitoring Device Elected	N	Tubings		Annulus	
Monitoring Device		Fittings	N	N	
FLM Canister Pressure		Actual Pressure			
Lease Status		Determined?			
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Well, OS6332000 was plugged and surface restoration was completed at the time of the inspection. There were no areas of concern.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.420662, -96.465689		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010790

Orientation: SSW

Date of Photo: 3/2/2026

Time of Photo: 9:45AM

Latitude: 36.420662

Longitude: -96.465689

Photographer: Matthew Allen

Description: This was the well location for OS6332000. Plugging operations were complete and surface restoration was completed. There were no areas of concern at the time of the inspection.