

**Well Inspection**  
**Environmental Protection Agency**  
**1201 Elm Street, Suite 500**  
**Dallas, Texas 75270**

|                                  |                                                                                                                                                                                                                                                                                                                                                                                                                             |                                                  |                        |                         |                                        |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|------------------------|-------------------------|----------------------------------------|
| <b>Inspector</b>                 | Jeanne Eckhart                                                                                                                                                                                                                                                                                                                                                                                                              | <b>Inspection Date</b>                           | 02/22/2023             | <b>Time</b>             | 16:10                                  |
| <b>Inspection Due</b>            | 2021-06-18T00:00:00Z                                                                                                                                                                                                                                                                                                                                                                                                        | <b>Operator Representative</b>                   | Binger Operations, LLC |                         |                                        |
| <b>Operator Info</b>             | Binger Operations, LLC<br>204 North Robinson, Suite 2300<br>Oklahoma City, OK 731026891<br>Phone: 405-687-0855                                                                                                                                                                                                                                                                                                              | <b>Inventory ID</b>                              | OK9109000              |                         |                                        |
|                                  |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>API Well No</b>                               |                        |                         |                                        |
|                                  |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Lease Name</b>                                | E Binger Unit          |                         |                                        |
|                                  |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Well ID</b>                                   | 72-3                   |                         |                                        |
| <b>Location</b>                  | SW 04 09N 10W                                                                                                                                                                                                                                                                                                                                                                                                               | <b>Status</b>                                    | Active                 | <b>Well Type</b>        | Enhanced Recovery                      |
| <b>Latitude</b>                  | 35.2784623                                                                                                                                                                                                                                                                                                                                                                                                                  | <b>Longitude</b>                                 | -98.2666295            |                         |                                        |
| <b>Inspection Reason</b>         | Other                                                                                                                                                                                                                                                                                                                                                                                                                       | <b>Responsible Company at Time of Inspection</b> | Binger Operations, LLC |                         |                                        |
| <b>Inspect No.</b>               |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Date Last MIT</b>                             | 06/19/2019             | <b>Last Test Result</b> | Acceptable                             |
| <b>Casing</b>                    | 4.5                                                                                                                                                                                                                                                                                                                                                                                                                         | <b>Tubing</b>                                    |                        | <b>USDW</b>             |                                        |
| <b>Monitoring Device Elected</b> | N                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>Tubings</b>                                   |                        | <b>Annulus</b>          | <b>AUTHORIZED</b>                      |
| <b>Monitoring Device</b>         |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Fittings</b>                                  | Y                      | Y                       | <b>Max Pressure</b> 5000               |
| <b>FLM Canister Pressure</b>     |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Actual Pressure</b>                           | 1600                   |                         | <b>Max Volume</b> 2000                 |
| <b>Lease Status</b>              | Active                                                                                                                                                                                                                                                                                                                                                                                                                      | <b>Determined?</b>                               | Compan<br>y Gage       |                         | <b>Max Inj Units</b> Barrels Per Month |
| <b>Barrel Monitor Hooked Up?</b> | N                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>Static Fluid Level</b>                        |                        |                         |                                        |
| <b>Barrel Fluid Level (%)</b>    |                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Determined?</b>                               |                        |                         |                                        |
| <b>Flowline Hooked Up?</b>       | Y                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>Injection Rate (bpd)</b>                      |                        |                         |                                        |
| <b>Injecting</b>                 | Y                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                  |                        |                         |                                        |
| <b>Inspection Comments</b>       | Inspectors Matthew Allen, Jeanne Eckhart, and Tamara Griffin conducted a routine injection well inspection on OK9109000. The injection well was actively injecting during the inspection. EPA enforcement staff will review this inspection data to determine compliance with EPA UIC regulations.                                                                                                                          |                                                  |                        |                         |                                        |
| <b>Inspector Signature</b>       | <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;"> <b>JEANNE ECKHART</b> </div> <div>             Digitally signed by JEANNE ECKHART<br/>             Date: 2023.03.21 11:32:45 -05'00'           </div> </div>                                                                                                                                            |                                                  |                        |                         |                                        |
| <b>Supervisor Signature</b>      | <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;"> <b>DAMON MCELROY</b> </div> <div>             Digitally signed by DAMON MCELROY<br/>             DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=DAMON MCELROY, 0.9.2342.19200300.100.1.1=68001003655653<br/>             Date: 2023.03.27 12:33:06 -05'00'           </div> </div> |                                                  |                        |                         |                                        |

## Appendix 1

### Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

|                                   |                      |                 |
|-----------------------------------|----------------------|-----------------|
| Location: 35.2784623, -98.2666295 |                      |                 |
| City: Binger                      | County/Parish: Caddo | State: Oklahoma |



**Photo File Name:** R0010017.JPG

**Orientation:** NW

**Date of Photo:** 02/22/2023

**Time of Photo:** 4:09 PM

**Latitude:** 35.2784623

**Longitude:** -98.2666295

**Photographer:** Tamara Griffin

**Description:** This was the injection well OK0226000 sign at the time of the inspection.




## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

### Photograph Log

Photo No. 2

|                                   |                      |                 |
|-----------------------------------|----------------------|-----------------|
| Location: 35.2784623, -98.2666295 |                      |                 |
| City: Binger                      | County/Parish: Caddo | State: Oklahoma |



**Photo File Name:** R0010018.JPG

**Orientation:** NW

**Date of Photo:** 02/22/2023

**Time of Photo:** 4:09 PM

**Latitude:** 35.2784623

**Longitude:** -98.2666295

**Photographer:** Tamara Griffin

**Description:** This was the injection well OK9106000 at the time of the inspection.