



Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

This report includes only factual information gained by documentation, onsite observations, and/or onsite interviews.

Inspector Name(s)	Chelsey Sherwood	Time In	8:00 AM	Start Date	November 28, 2023
		Time Out	8:30 AM	End Date	November 28, 2023
Inspector's Organization	EPA Region 6, Enforcement and Compliance Division, Water Resources Section				
Organization Requesting Inspection (if different)	N/A				
Inspection Type	Evaluation	Inspection Status	Original		
Site Name	Richard Sturgis				
Site Address*	Frost Road				
City*	Arkadelphia	County*	Clark	State*	AR Zip Code* 71923
Mailing Address*	3111 SE 41st PL				
City*	Ocala	County*	Marion	State*	FL Zip Code* 34480
Latitude*	34.18868	Longitude*	-93.06819		
Estimated Size of Site (acres)	23	Is there a home on the site?	☐ Yes ☒ No		
Inspector Signature	CHELSEY SHERWOOD	Digitally signed by CHELSEY SHERWOOD Date: 2024.01.22 16:45:38 -06'00'	Date	1/22/2023	
Supervisor Signature	THOMAS NYSTROM	Digitally signed by THOMAS NYSTROM Date: 2024.01.23 06:39:25 -06'00'	Date		

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	Richard Sturgis	Start Date	November 28, 2023
		End Date	November 28, 2023
Inspection Purpose	Initial site visit		
Opening Conference			
☐ Presentation of Inspector Credentials Name and Title (Use N/A if owner/operator not available to join the inspection) N/A			
☐ Opening Conference Name of person authorizing access if applicable N/A			
Notes from Opening Conference N/A			
☐ Access Issues if Any Describe N/A			
Inspection Observations and Sample Collection			
Site Owner/Site Operator/Responsible Party (Name, title and contact information) Richard Sturgis, Owner			
Additional Persons Present at Inspection N/A			
General Site Characteristics (layout of property, etc.) The property is north of frost road and was originally forested, but has now been cleared. Refer to map attachments for details.			
Purpose and Need for Discharge of Dredged and/or Fill Material Unknown			
Site Overview (Past inspections, site description, permits, etc.) Unknown			
Scope of Inspection (Areas inspected or not inspected) This property was inspected from frost road. Refer to maps and photo log.			

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	Richard Sturgis	Start Date	November 28, 2023
		End Date	November 28, 2023
Environmental Conditions (e.g., wind, rain, smoke, dust, temperature, snow)			
~49 degrees F, Sunny			
Field Work Conducted			
This site was inspected from the road. Pictures were taken for documentation.			
Closing Conference			
Documents Received and/or Requested During the Inspection			
N/A			
Compliance Assistance Provided (If any)			
N/A			
Observations Relayed to Site Owner/Operator			
N/A			
Actions Taken by Owner/Operator During the Inspection (If any)			
N/A			
Potential Issues of Concern Including Regulatory Citations			
There were concerns of possible activity without a 404 permit.			
Attachments*			
☒ Maps and Sketches ☒ Photographs (including location) and Photo Log ☐ Other (SSIP, Wetlands Delineation Forms, etc.)			
N/A			
Additional Notes			
N/A			