

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's (EPA's) inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	May 25, 2022
EPA Region/Program Conducting Inspection:	EPA Region 4/Mobile Source Program
Company Name:	Gabby's Auto Werks
Facility Name:	Gabby's Auto Werks
Facility Physical Location: (street address, building/unit #)	7835 NW 55th Street
(city, state, zip code)	Doral, Florida 33166

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Tony Spann

Field Inspector Name

Spann, Tony Digitally signed by Spann, Tony
Date: 2022.07.06 13:03:50 -04'00'

Signature

Date

Jason Dressler

Name of Approving
Official

Chief, NAES

Title

JASON DRESSLER

Digitally signed by JASON
DRESSLER
Date: 2022.07.06 14:14:35 -04'00'

Signature

Date

FACILITY INSPECTION WORKSHEET

(Supplemental notes or narrative format may be used as preferred).

General Inspection Information			
Facility Name:	Gabby's Auto Werks	Inspection Date	5/25/2022
Facility Address:	7835 NW 55th Street Doral, FL 33166	Arrival/Departure Time	10:06 am 11:10 am
		Inspection Number/ID:	3601431357
Primary Facility Representative & Title:	Gabriel Szuster, Owner	Inspector(s):	Tony Spann (Lead) Carrie Griffith Aleeka Broner
Facility Contact Phone/Email:	786-402-7641 gawracing@aol.com		
Time Inspector Presented Credentials:	10:08 am	Compliance Assistance Reference Materials Provided to Facility	☒ SBREFA Form ☒ Exhaust Repair Guidelines ☐ Memo 1A ☐ Tampering Brochure ☐ Engine Switch Fact Sheet ☐ Other:
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No		
	Gabriel Szuster		
Photographer Name:	Carrie Griffith	Photograph Range:	N/A
Notes (e.g. compliance actions taken by facility, purchased samples, other relevant background, etc.):	Facility did not claim any photographs taken as CBI.		

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts (hardware or software)		
☐	Sells aftermarket part sales (including drop shipments)		
☒	Service shop	Provides repair services for light, medium, and heavy-duty trucks, as well as other vehicles. The facility also services fleet vehicles. Inspectors observed service invoices for vehicles serviced at the facility. All service invoices observed were handwritten.	Services 40 to 50 vehicles per month
☐	Fleet		
☐	Other:		

Personnel Interviewed			
Name	Title/Position	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Gabriel Szuster	Owner	786-402-7641 gawracing@aol.com	Spann
Willie Gonzalez	Technician	786-402-7639 gawracing@aol.com	Spann

Documents Requested		
Document(s)	Status	Notes/Comments
Service invoices for vehicles serviced from 3/1/22 to 5/25/22	☐ Document(s) Provided ☒ Will Provide After Inspection ☐ Document(s) Denied ☐ Other (see notes)	Hard copies of May service invoices examined by inspectors on site. Facility did not claim any documents observed as CBI. Facility provided the requested records on 6/30/22.
	☐ Document(s) Provided ☐ Will Provide After Inspection ☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection ☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection ☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection ☐ Document(s) Denied ☐ Other (see notes)	

Vehicles Inspected/Observed				
VIN (last 4 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Data Obtained? (Yes/No)	Observations (e.g., Who Performed Apparent Tampering?)
N/A				