

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/23/2024	Time	13:35
		Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS0810000		
		API Well No			
		Lease Name	LONG		
		Well ID	4		
Location	NW 02 22N 07E	Status	Active	Well Type	Dual Completion
Latitude	36.418832	Longitude	-96.526304		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT	10/29/2016	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 780
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed the location for well OS0810000. The casing had been cut off below ground and the surface had been restored.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.418832, -96.526304		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010496

Orientation: N/A

Date of Photo: 7/23/2024

Time of Photo: 1:36 PM

Latitude: 36.418832

Longitude: -96.526304

Photographer: Matthew Allen

Description: This was well OS0810000 after surface restoration was completed.