

Employers Insurance of Wausau

HOME OFFICE: WAUSAU, WISCONSIN



FOR

Mr. John W. Ward, Vice-President
Haveg Industries, Incorporated
900 Greenbank Road
Wilmington, Delaware 19808

August 22, 1966

CONCERNING

900 Greenbank Road
Wilmington, Delaware

SERVICE BY


W. J. Uber, industrial hygiene consultant, and
C. J. Ehrhart, safety consultant, on August 2, 1966

PERSONS CONTACTED

W. U. Reybold, plant engineer
Helen Fraticelli, R.N.

REPORT SUMMARY

Industrial Hygiene Survey



"We called on this policyholder to review the proposal for a new materials handling system in the asbestos treating department. Our study of the asbestos dust hazard had indicated that additional controls were required to reduce the concentration of airborne asbestos dust to which workers were exposed.

"An index of performance for the dust collectors is the static suction pressure produced on the clean and dirty sides of the collector, and we suggested the use of a permanently mounted manometer connected to both sides of the collector for easy determination of these pressures. Mr. Reybold will provide for this gaging device.

"Mrs. Fraticelli, R.N., reviewed for us the status of chest X rays, which are on schedule for workers exposed to asbestos.

"We suggested to Mr. Reybold that when the modifications to the asbestos handling system have been completed and the weather is cold enough to operate with doors and windows closed, a follow-up asbestos dust study be performed, and this will be arranged."

HO 85

cc: Mr. H. B. Haney; Mr. W. U. Reybold

This confirmation of service concerns only such conditions and practices as were observed and considered at the time of this call. It is not intended to indicate that all other hazards are adequately controlled.

If you have any comments or questions concerning this report, write to C. H. Elsby, Vice-President, Safety & Health Services.

Haney #10

C-2 000200