

FILE NAME: Powhatan (PHN)

DATE: 1954-1968

DOC#: PHN010

DOCUMENT DESCRIPTION: Govt Inspection Reports

DIVISION OF INDUSTRIAL HEALTH

INDUSTRIAL PLANT RECORD

PLANT Powhatan Mining Co. Inc. LOCATION Woodlawn
 PLANT OFFICIAL AND TITLE Frank M. L. L. L.
 PRODUCTS MANUFACTURED OR SERVICE Asbestos
 NUMBER OF EMPLOYEES 12 MALE 10 FEMALE 2 SHIFTS 1 REST PERIOD 1 hour 15 min
 PLANT LAYOUT: NUMBER OF BUILDINGS 2 TYPE open air OTHER STRUCTURES none
 SURVEYED BY R. J. L. ACCOMPANIED BY F. Smith TITLE Superintendent DATE 9/15/47

D. I. Schlemmer MEDICAL DATA
 PHYSICIAN D. I. Schlemmer NURSE no
 PREEMPLOYMENT EXAM. (5) yes PERIODIC (5) yes
 FIRST AID: KIT yes ROOM no WORKER no
 SICK BENEFIT ASSOCIATION Home Blue Cross
 SICKNESS RECORD: O. D. no NON O. D. no

PLT. SAFETY DATA
 DIRECTOR Dennis Smith MEETINGS none
 ACCIDENTS: F.R. PLANT 2 R. AV. IND. no
 S.R. PLANT no S. R. AV. IND. no
 HAZARDS: PASSAGEWAY no STAIRS no FLOOR no
 BLDG. DEFECTS no FIRE no ESCAPES no

ENVIRONMENTAL DATA
 HAZARDOUS MATERIALS HANDLED: asbestos and silica, muriatic acid
 PROTECTIVE EQUIPMENT: FURNISHED rubber gloves & aprons, dust-free respirators
 NEEDED no And moist respirators, goggles
 LIGHTING: ARTIFICIAL yes TYPE inc. bulb glare NATURAL yes GLARE no
 VENTILATION: ARTIFICIAL GENERAL good LOCAL screening NATURAL good
 HEAT BUILDING yes ST. & SUBPROCESS no CONTROL good
 FATIGUE FACTORS: NOISE no SEATS yes STRAIN no OTHER no

SANITATION
 WATER SUPPLY: SOURCE city SEWAGE DISPOSAL city WASTE DISPOSAL city
 DRINKING FACILITIES: TYPE DISPENSER yes ADEQUATE yes CONVENIENT yes
 TOILET FACILITIES: MALE yes FEMALE yes CLEAN yes DEFECTIVE no ADEQUATE yes CONVENIENT yes
 WASHING FACILITIES: LAVATORIES yes SHOWERS yes HOTWATER yes SOAP yes TOWELS yes CONVENIENT yes
 POSSIBLE CROSS-CONNECTIONS no INSECT OR RODENT INFESTATION no
 REST ROOM no LOCKERS no CLOAKROOM no CHANGE HOUSE no
 INSANITARY PRACTICES no

MISCELLANEOUS
 EATING FACILITIES: CAFETERIA no NUTRITIONIST no EATING ROOM no
 HOUSEKEEPING fair WINDOWS CLEAN no WALLS AND CEILINGS no
 OVERCROWDING no INSURANCE CARRIER yes UNION no

REMARKS Notation
GLEN FALLS - VISIT EVERY 304 NOS
(1) Ball mill operation is very noisy. This process is
not however done to frequently.
(2) Air facilities are available in the building about 50 ft
away. There is also water available in the building
building where the men can wash
(3) Considerable amounts of asbestos dust exists
on walls, pipes etc.
(4) X-rays taken and findings to M.D. - supposedly

[illegible]