

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/04/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Basa Resources, Inc.	
Facility Name:	HL Griffen Lease	
Facility Physical Location:	32.168465, -94.738718	
(city, state, zip code)	Price, Texas 75654	
Mailing address:	14875 Landmark Blvd., Ste. 400	
(city, state, zip code)	Dallas, Texas 75254	
County/Parish:	Rusk County	
Facility Phone Number	214-580-5206	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011259	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Basa Resources, Inc. oil and gas facility located near Price, Texas on 03/04/2020 for an unannounced inspection. There were no representatives of Basa Resources, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as HL Griffen Lease and has the state identification number: RRC No. 06111.

Section II - OBSERVATIONS

I observed that there was not a secondary containment area around the tank battery during the inspection. I observed surface damage indicating spill damage from produced water (brine) spills northeast of the tank battery near some nearby trees. I observed a pit near the facility that had a drainpipe and valve on it.

Section III – AREAS OF CONCERN

There was no secondary containment.

Section IV – FOLLOW UP

EPA water enforcement will refer this to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A