Applied Environmental Services
"Consultants in Wastes Management and Environmental Control"

ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO SUITE 320 EL PASO, TEXAS 79902 (915) 533-4108



24 December 1987

Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Sample No.	Time-m	Flow-l	Fibers/cc
S-54, area I, c-pipeway area	420	15	<0.01
S-55, area I, c-pipeway personal	420	3.2	0.02

Sincerely,

Howard G. Applegate
Ph.D.

Chevron BB
015580

AES
Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL

PROJECT: CHEVRON

DATE: DECEMBER 23,1987

ANALYZED BY: DR. HOWARD APPLEGATE

DATE: DECEMBER 24, 1987

Chevron BB
015581

SAMPLE NO.	S-54	S-55						
SAMPLE LOCATION	AREA I "C" PIPEWAY AREA SAMPLE	AREA I "C" PIPEWAY PERSONAL SAMPLE						
FILTER SIZE (mm)	25	25						
START TIME	9:20 am	9:25 am						
END TIME	4:20 pm	4:25 pm						
RATE OF FLOW (1pm)	15	2						
TOTAL TIME (hrs)	7	7						
VOLUME SAMPLED (1)	6300	840						
RESULTS (f/cc)	< 0.01	0.02						