

EPA OECA Air Enforcement Division INSPECTION REPORT

Inspection Date(s):	03/08/2023		
Media:	Air		
Regulatory Program(s)	Title II Mobile Sources		
Company Name:	BOR Motorsports		
Facility Name:	BOR Motorsports Dealership		
Facility Physical Location:	5750 N Sam Houston Pkwy E STE 603		
(city, state, zip code)	Houston, TX 77032		
Mailing address:	5750 N Sam Houston Pkwy E STE 603		
(city, state, zip code)	Houston, TX 77032		
County/Parish:	Harris County, TX		
Facility Contact:	Michael Mccullah	Owner	
	832-766-5651		
FRS Number:	N/A		
Identification/Permit Number:			
Media Number:	N/A		
NAICS:	N/A		
SIC:	N/A		
Facility Representatives:	Haleigh Mccullah	Receptionist	832-766-5651
	{name}	{title}	{phone no.}
	{name}	{title}	{phone no.}
	{name}	{title}	{phone no.}
EPA Inspectors:	Mario Jorquera	OECA/OCE/AED/VEEB	202-564-1079
	Victor Aguilar	OECA/OCE/AED/VEEB	202-564-9679
	{name}	{affiliation/mailcode}	{phone no.}
State Inspector(s):	{name}	{affiliation/mailcode}	{phone no.}
	{name}	{affiliation/mailcode}	{phone no.}
Other Inspector(s):	{name}	{affiliation/mailcode}	{phone no.}
	{name}	{affiliation/mailcode}	{phone no.}
Metadata	Title:	BOR Motorsports Dealership Houston, TX Inspection	
	Author:	Mario Jorquera	
	Subject:	Inspection Report	
	Keywords:	Inspection of nonroad motorcycle and ATV dealership	
EPA Lead Inspector Signature/Date	Mario Jorquera MARIO {Inspector name} JORQUERA	Digitally signed by MARIO JORQUERA Date: 2023.06.09 17:16:41 -04'00'	Date
Supervisor Signature/Date	Mark Palermo {Supervisor name}		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA HQ Air Enforcement Division, Vehicle and Engine Branch inspectors Victor Aguilar and Mario Jorquera arrived at the BOR Motorsports dealership at 12:00 pm on March 08, 2023 for an unannounced inspection. We met with the receptionist, Haleigh Mccullah at the front desk for an Opening Conference. We presented our credentials to Haleigh Mccullah and informed her that this was an EPA inspection to review whether the equipment available for sale at the dealer was certified by the EPA for sale in the U.S. The scope of the inspection was an evaluation of the compliance status of several pieces of equipment being offered for sale at the facility.

FACILITY DESCRIPTION

Facility is a storefront retail outlet for motorsports equipment located in a warehouse-type building. The layout consisted of a back room for repairs and parts storage, an office, and display floor space for some 30 or so vehicles, including ATVs, UTVs, karts and nonroad motorcycles.

Facility appeared to have 3 employees: The owner/manager, the receptionist, and a mechanic.

Facility operates 5 days a week, about 7 hours each day.

Section II – OBSERVATIONS

Inspector Aguilar talked to the owner, Michael Mccullah and asked him if he had any KXD motorcycles. He stated that he no longer sells KXD bikes. These were of interest to EPA from prior inquiries.

EPA inspectors also asked him about other local dealerships that also sell dirt bikes and Michael provided the following information:

Electron X – main Apollo carriers

Flying Scooter – also carries Apollo

BMC Motorsports – sells x-moto, Donfang, Kandy and Massimo go-karts

At 12:18pm, both EPA inspectors began conducting inspections.

Complete inspection reports were performed on one X-moto dirt bike and one Commander Go-Kart

Inspectors also looked for the ECI label on several more vehicles:

Massimo/KD-2000GKM-2/ 177cc/Go-Kart (ATV)/ Manufacturer: Zhejiang Kangdi Tech Group/
EFN: MJASX.177GKH/ Importer: Jass Motorsports

Dongfang Motor/ DF125GKS/ 110 cc/ Go-Kart (ATV)/ Manufacturer: Ningbo Dongfang Lingyun/
EFN: MDGFX.110GCR/ Importer: Dongfang Motor Inc.

Maxtrade Mountopz/ Coolster Mountops-150 (ATV-3150CXC)/ 150 cc/ ATV/ Manufacturer:
Zhejiang QIYE Scooter Co./ Importer: Maxtrade/ EFN: LMXTX.1705A

At 1:12pm, the EPA inspectors notified Haleigh Mccullah that the inspection was completed and what our general findings were. EPA inspector Mario also informed her that if we required additional information, EPA would reach out via email.

Section III – AREAS OF CONCERN

EPA inspectors found no noncompliance and so have no areas of concern.

Section IV – FOLLOW UP

None

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – Photos DSCN 1662 to DSCN1701 taken with Nikon camera on 03/08/2023

Appendix 2 – Inspection sheets for two inspected machines