

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/13/2026	Time	09:20
		Operator Representative	McCann Resources, Inc		
Operator Info	McCann Resources, Inc 1613 West 6th Street Bartlesville, OK 740033404 Phone: 918-337-4747	Inventory ID	OS5437000		
		API Well No			
		Lease Name	Mullendore		
		Well ID	9		
Location	NE 17 29N 11E	Status	Active	Well Type	Disposal
Latitude	36.996332	Longitude	-96.131414		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	McCann Resources, Inc		
Inspect No.		Date Last MIT	04/01/2025	Last Test Result	Acceptable
Casing	4.5	Tubing	2.857	USDW	380
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 400
FLM Canister Pressure		Actual Pressure	0		Max Volume 3000
Lease Status	Inactive	Determined?	Other		Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level	644.51		
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	At the time of the inspection, well OS5437000 was disconnected. The tubing fluid level was observed to be 644.51' below the tubing cutoff valve. The permit requires a standard annulus pressure test and the well was overdue for MIT.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.996332, -96.131414		
City: Bowring	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010847

Orientation: ESE

Date of Photo: 04/13/2026

Time of Photo: 9:20AM

Latitude: 36.996332

Longitude: -96.131414

Photographer: Matthew Allen

Description: This was well OS5437000 at the time of the inspection. The well was overdue for MIT.