

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	03/31/2021	
Media Program:	Water	
Regulatory Program(s)	CWA – NPDES, Produced Water	
Company Name:	WWW Oil Company	
Facility Name:	Whitetail-Stuart	
Facility Physical Location:	36.785168, -96.268143	
(city, state, zip code)	Pawhuska, OK 74056	
Mailing address:	2300 N. McKenzie Rd. (P.O. Box 1138)	
(city, state, zip code)	Pawhuska, Oklahoma 74056	
County/Parish:	Osage County, Oklahoma	
Facility Phone Number	702-303-7954	
Facility Contact:	Mike Wachtman	
FRS Number:	N/A	
Identification/Permit Number:	OKU000872	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Kent Sanborn	EPA, 6ECDW	EPA Lead Inspector
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		19 APR 2021
	Guy Tidmore	Date

Section I – INTRODUCTION

Purpose of inspection

EPA Region 6 inspector Kent Sanborn arrived at the WWW Oil Company oil and gas facility at 3:00 pm on 03/31/2021 for an inspection of a lease that has had a discharge in the past. There were no facility representatives present at the site. The inspection was conducted under the authority of the Clean Water Act (CWA) to assess a previously reported spill from a brine disposal facility. The scope of the inspection is to assess unauthorized discharges and impacts of nearby water resources under the CWA.

Facility Description

The facility is a brine and injection well facility and was previously known as the “Watchman-Schroeder, Inc. (Whitetail-Stuart Lease)” facility.

Section II – OBSERVATIONS

I had the following observations during the inspection:

The secondary containment pit at the facility was ½ full of fluids with oil on top. The pit was not seeping and was not running over. Damage from a previous spill was evident, but some restoration has taken place. A gas pump was present to keep the pit empty.

Were control measures put in place?	N/A
National Response Center (NRC) notified?	N/A
Remedial action ongoing?	N/A
Downstream Observations?	N/A
Upstream Observations?	N/A
Spill Ongoing?	N/A
Spill reached waterbody?	N/A
Aquatic Life Kill/Damage?	N/A
Vegetation damage?	N/A

Section III – AREAS OF CONCERN

The following areas of concern were identified:

- Operator needs to empty pit and keep empty.

Section IV – FOLLOW UP

The following follow up actions that are recommended for EPA are:

- None

Section V – RESOURCES

Below are compliance resources for oil and gas facilities:

- To report spills associated with your facility, call: **1-800-424-8802**, for more information: <https://www.epa.gov/pesticide-incidents/how-report-spills-and-environmental-violations>.
- For information regarding Spill Prevention, Control, and Countermeasure (SPCC) program: <https://www.epa.gov/oil-spills-prevention-and-preparedness-regulations/facility-owneroperators-guide-oil-pollution>.
- For information regarding Underground Injection Control (UIC) (Safe Drinking Water Act): <https://www.epa.gov/uic>.