



Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

This report includes only factual information gained by documentation, onsite observations, and/or onsite interviews.

Inspector Name(s)	Chelsey Sherwood	Time In	12:00 PM	Start Date	October 10, 2024
		Time Out	1:10 PM	End Date	October 10, 2024
Inspector's Organization	EPA Region 6, Enforcement and Compliance Division, Water Resources Section				
Organization Requesting Inspection (if different)	N/A				
Inspection Type	Evaluation	Inspection Status	Original		
Site Name	Peel Compton Foundation				
Site Address*	N/A				
City*	Bentonville	County*	Benton	State*	AR Zip Code* 72712
Mailing Address*	312 N Main Street				
City*	Bentonville	County*	Benton	State*	AR Zip Code* 72712
Latitude*	36.38722	Longitude*	-94.23859		
Estimated Size of Site (acres)	1	Is there a home on the site?	☐ Yes ☒ No		
Inspector Signature	CHELSEY SHERWOOD Digitally signed by CHELSEY SHERWOOD Date: 2024.12.05 15:34:24 -06'00'			Date	12/5/2024
Supervisor Signature	RUBEN ALAYON-GONZALEZ Digitally signed by RUBEN ALAYON-GONZALEZ Date: 2024.12.06 11:18:49 -06'00'			Date	

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	Peel Compton Foundation	Start Date	October 10, 2024
		End Date	October 10, 2024
Inspection Purpose	Initial site visit		
Opening Conference			
☐ Presentation of Inspector Credentials Name and Title (Use N/A if owner/operator not available to join the inspection) N/A			
☐ Opening Conference Name of person authorizing access if applicable N/A			
Notes from Opening Conference N/A			
☐ Access Issues if Any Describe N/A			
Inspection Observations and Sample Collection			
Site Owner/Site Operator/Responsible Party (Name, title and contact information) Peel Compton Foundation Phone number: 479-254-3870			
Additional Persons Present at Inspection Pablo Bacon with the Little Rock District of the US Army Corps of Engineers			
General Site Characteristics (layout of property, etc.) This property is located on an approximately 300 acre Mountain Biking Park and is primarily forested. An unnamed tributary to McKisic Creek flows south to north through the property and is surrounded by biking trails with several crossings. Refer to map attachments and photographs for details.			
Purpose and Need for Discharge of Dredged and/or Fill Material The purpose was to remove the low water bridge crossing and restore the stream channel and banks.			
Site Overview (Past inspections, site description, permits, etc.) The Corps has done inspections in the past before the restoration was completed.			
Scope of Inspection (Areas inspected or not inspected) We inspected the area the stream was restored as well as upstream and downstream of the site.			

Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	Peel Compton Foundation	Start Date	October 10, 2024
		End Date	October 10, 2024
Environmental Conditions (e.g., wind, rain, smoke, dust, temperature, snow)			
~84 degrees F, sunny. This area has been in a drought with no precipitation since September 1, 2024.			
Field Work Conducted			
We assessed the stream restoration project as well as observed young of year fish and sampled for aquatic macroinvertebrates in the project area. Pictures were taken for documentation.			
Closing Conference			
Documents Received and/or Requested During the Inspection			
N/A			
Compliance Assistance Provided (If any)			
N/A			
Observations Relayed to Site Owner/Operator			
N/A			
Actions Taken by Owner/Operator During the Inspection (If any)			
N/A			
Potential Issues of Concern Including Regulatory Citations			
This inspection was for compliance monitoring to assess the area of the low water bridge removal and the success of the stream restoration. We found no issues of concern at the time of inspection. This report will be sent to the Little Rock Corps District. Refer to photos and map attachments for site inspection details.			
Attachments*			
☒ Maps and Sketches ☒ Photographs (including location) and Photo Log ☐ Other (SSIP, Wetlands Delineation Forms, etc.)			
N/A			
Additional Notes			
N/A			

Appendix 1

Photograph Log



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.38727, -94.23877		
City: Bentonville	County/Parish: Benton	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
IMG_0094.JPG	10/10/2024, 12:31 PM	Chelsey Sherwood	Showing area where the low water bridge was removed and the stream restored with natural rock and riffle pool complex. Picture taken facing north, downstream.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.38724, -94.23875		
City: Bentonville	County/Parish: Benton	State: Arkansas



Photo File Name	Date and Time of Photo	Photographer	Description
IMG_0095.JPG	10/10/2024, 12:31 PM	Chelsey Sherwood	Showing area where the low water bridge was removed and the stream channel and banks restored. Picture taken facing south, upstream.


Peel Compton Foundation Photo Locations



12/5/2024, 6:56:14 AM

-  Subwatershed (HUC12)
-  Catchment

- Network Flowline
-  Stream/River, Intermittent



© 2024 Microsoft Corporation © 2024 Maxar ©CNES
(2024) Distribution Airbus DS, US EPA Office of Water