

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/29/2024	Time	08:30
		Operator Representative	Helmer Oil Corp.		
Operator Info	Helmer Oil Corp. P.O. Box 1325 Pawhuska, OK 74056 Phone: 918-645-6803	Inventory ID	OS3275000		
		API Well No			
		Lease Name	Fred		
		Well ID	SWD 3		
Location	NE 16 25N 08E	Status	Inactive	Well Type	Disposal
Latitude	36.650965	Longitude	-96.444273		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Helmer Oil Corp.		
Inspect No.		Date Last MIT	03/16/2023	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 353
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Speedy Well Service (SWS) run in well OS3275000 to 1420 feet below the surface and load the well with mud. SWS then spotted 35 sacks of class A cement. After waiting 4 hours SWS tagged the top of the bottom cement plug at 1200 feet below the surface. SWS pulled up hole to 400 feet and pumped 50 sacks of class A cement but was unable to fill the well to the surface. SWS shutdown to allow cement to cure.				
Inspector Signature					
Supervisor Signature					