

R. I. 3465

TABLE 5. - Record of rock dust analyses

Date	By whom collected	Heading and location	Date analyzed	Percent of incombustible		
				Bottom	Roof	Sides
9/1/38	J.H.T.	#4 east at 7380	9/1/38	86	86	86
		#5 east at 7350	9/1/38	70	70	70
		#6 east at 7325	9/1/38	66	66	66
		#7 east at 7310	9/1/38	64	64	64
		#1 north at 500	9/1/38	65	65	65
		#2 north at 515	9/1/38	64	64	64
		#3 north at 490	9/1/38	72	72	72
		#4 north at 495	9/1/38	86	86	86
		#5 north at 525	9/1/38	70	70	70
		#6 north at 510	9/1/38	72	72	72
9/8/38	J.H.T.	#7 north at 530	9/1/38	60	60	60
		#1 entry, 1 south at 40	9/8/38	60	60	60
		#1 entry, 1 south at 2040	9/8/38	78	78	78
		#1 entry, 1 south at 4000	9/8/38	80	80	80
		#2 entry, 1 south at 40	9/8/38	80	80	80
		#2 entry, 1 south at 2000	9/8/38	88	88	88
		#2 entry, 1 south at 4040	9/8/38	76	76	76
		#3 entry, 1 south at 40	9/8/38	70	70	70
		#3 entry, 1 south at 2040	9/8/38	58	58	58
		#3 entry, 1 south at 4100	9/8/38	76	76	76
		#4 entry, 1 south at 40	9/8/38	82	82	82
		#4 entry, 1 south at 2000	9/8/38	85	85	85