#10

GENERAL REFRACTORIES CO.
STEEL SALES CALL REPORT

Salesman: W. R. Fields

Call Date: 3/11/70

	Name	Title
COMPANY: Youngstown Sheet & Tube	Jim Scanlon	O.H. Supt.
LOCATION: Brier Hill Works, Youngstown, Ohio	Bob Leddon	Asst " "
SHOP:	Fitz Helton	Molson Supt.
CONTACTS		

CALLS: Made To-Date: ____ Planned Per Year. CALL DATES: Last ____ ; Next ____

PURPOSE AND OBJECTIVE OF CALL: Roof installation

PLAINTIFF'S EXHIBIT
COR-16

FURNACE STATUS:

No. and Type																
General Conditions																
Furnace Section (Fill In)	Refrac. Material	No. Heats	Life Expec.	Refrac. Material	No. Heats	Life Expec.	Refrac. Material	No. Heats	Life Expec.	Refrac. Material	No. Heats	Life Expec.	Refrac. Material	No. Heats	Life Expec.	

INSTALLATION & OPERATING INFO: Installed 15" H-22 M.E. and Tabled roof on #10 Lee.

Installation went very smoothly. They drove 3 keys about 1½" and will tie the roof up before pulling centers.

REFRACTORY PERFORMANCE: No additional expansion rows used in the rens (3/4" asbestos was taken the ravine). They did use 1/8" asbestos every 9" longitudinally.

The brick layers liked our tabs. — Not sharp like the regular Tabs of other DB brick.

Centers are to be pulled next Monor Tues. I told return then to inspect the keys and go to brick count.

SALES { OPPORTUNITIES / PROBLEMS } & ACTION REQ'D:

This furnace probably will not start up for a Month or so Dale. In all Instances one operating right man.