

ENVIRONMENTAL SURVEY SAMPLE RECORD

DATE: 3-22-73

BUILDING NO. A-1876	PROCESS Cutting asbestos gaskets	SUPERVISOR Harold Hewett	
MATERIAL OR CHEMICAL Asbestos	SAMPLING METHOD Air	TRAPPING MEDIUM 47 mm. filter paper	
TV EQUIPMENT M24 pump	FLOW INDICATOR 10	SAMPLING RATE	WIND DIR. —
		VELOCITY —	TEMP —

REMARKS

Area of cutting is upstairs in A-1876 in ~~South side~~ North side of bldg. Table top has neoprene cork material on it. The floor has not been swept for several days

Sample No.	Container No.	SAMPLE DESCRIPTION	TIME			Sample Volume	Analysis
			Start	Stop	Δ		
1	Pump 1	Mr. Gummage cutting asbestos gaskets	8:15 AM	8:18 AM	3 min	7.71	204
2	Pump 2	Mr. Gummage cleaning up area with broom. Pump #2 at top of stairway. (In breathing zone) Not on Mr. Gummage	8:25	8:27	2 min	5.38	72
3	Pump 2	At top of stairway during cutting of asbestos gaskets at cutting table. Table top is a neoprene cork material	8:15	8:18	3 min	8.07	288
4	Pump 1	Mr. Gummage cleaning up area with broom. Sweeping top of table and floor up.	8:25	8:28	3 min	7.71	156

PLAINTIFF'S EXHIBIT

DOW-2680

ST0014486