

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	1/27/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Edge Oil Company, Inc.	
Facility Name:	Eric Lease	
Facility Physical Location:	36.224712, -96.553143 (Sect. 10, T 20N, R 7E)	
(city, state, zip code)	Cleveland, Oklahoma 74020	
Mailing address:	123 S. Broadway	
(city, state, zip code)	Cleveland, Oklahoma 74020	
County/Parish:	Pawnee County	
Facility Phone Number	918-645-7694	
Facility Contact:	Michael Edgerton	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		28 FEB 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Edge Oil Company, Inc. oil and gas facility located near Cleveland, Oklahoma on 01/27/2020 for an unannounced inspection. There were no representatives of Edge Oil Company, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the Eric Lease and is southeast of Hallet, Oklahoma.

Section II - OBSERVATIONS

During the inspection, I observed that the tank battery was overgrown with vegetation. The secondary containment was inadequate due to the berms not being maintained properly.

Section III – AREAS OF CONCERN

The facility was overgrown with vegetation and the secondary containment berms were inadequate.

Section IV – FOLLOW UP

EPA water enforcement will conduct a follow up inspection in approximately 3 months and will refer this facility to the EPA R6 SPCC program.

Section V – LIST OF APPENDICES

N/A