

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>K</td><td>Y</td><td>S</td><td>1</td><td>5</td><td>3</td><td>0</td><td>1</td><td>4</td><td>6</td></tr><tr><td>2</td><td>0</td><td>2</td><td>4</td><td>-</td><td>1</td><td>0</td><td>-</td><td>2</td><td>2</td></tr></table>												K	Y	S	1	5	3	0	1	4	6	2	0	2	4	-	1	0	-	2	2
						K	Y	S	1	5	3	0	1	4	6																						
						2	0	2	4	-	1	0	-	2	2																						
						Year-Month-Day: <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>2</td><td>0</td><td>2</td><td>4</td><td>-</td><td>1</td><td>0</td><td>-</td><td>2</td><td>2</td></tr></table>												2	0	2	4	-	1	0	-	2	2										
2	0	2	4	-	1	0	-	2	2																												
EPA Permit # (or RA): <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>R</td><td>A</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>												R	A																								
R	A																																				
						Page <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>1</td></tr></table> Of <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>2</td></tr></table>												1	2																		
1																																					
2																																					
Inspector(s): <u>Carol Chen</u> (lead), <u>Lonnie Dorn</u> Start Time: <u>11:14 am</u>																																					
End Time: <u>11:15 am</u>																																					
Facility Contact Information	Facility Name: <u>Slone Energy, LLC</u>																																				
	Street Address: <u>8966 KY RT 40 West, P.O. Box 220</u>																																				
	City: <u>Oil Springs</u> County: <u>Magoffin</u> State: <u>KY</u> Zip: <u>41238</u>																																				
	Nature of Business: <u>oil production</u>																																				
	Facility Owner/Operator: <u>Mr. S. Chris Salone, PE</u> Phone: <u>606.297.5330 work</u>																																				
	Email: <u>chrislone@sloneenergy.com</u>																																				
	Facility Contact (if different): _____ Phone: <u>606.225.2206 cell</u>																																				
	O/O Mailing Address: _____																																				
City: _____ County: _____ State: _____ Zip: _____																																					
Well Data from File	Well Name & #: <u>J. P. CONLEY #W-5</u>																																				
	Well Type (see table): <u>Class II-R, Enhanced Oil Recovery (EOR)</u> State Permit: _____																																				
	Latitude (°N): <u>37.77875</u> Longitude (°W): <u>-83.00994</u> Elevation (ft): _____																																				
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing																																				
	☐ Other: <u>4 1/2" production casing</u>																																				
	Total Depth (ft): _____ Inner Casing Size (in): <u>2 3/8"</u> Tubing Size (in): <u>1"</u> Packer Depth (ft): _____																																				
Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) _____ Bottom(ft): _____ Max. Injection Pressure (psig): _____																																					
Field Measurements and Observations	Latitude (°N): <u>37.77837</u> Longitude (°W): <u>-83.01039</u> Elevation (ft): _____																																				
	EPA GPS ID: <u>S75332</u> Well Status (see table): <u>AC</u> If not Active, Reported Date Last Active: _____																																				
	Nature of Injected Fluid(s) if any: <u>Produced Waters (PW)</u>																																				
	General Condition of the Well Site: _____																																				

	Notes & Comments (include discrepancies from database values): _____																																				

	<u>The injection line is connected, feels icy cold. Produced waters are being injected for</u>																																				
	<u>enhanced oil recovery. Gauges were not found to monitor injection and annulus pressures.</u>																																				
	<u>Wellcap shows corrosion.</u>																																				
See reverse for additional observations, comments and photo log																																					
UIC Inspector																																					
Name: <u>Carol Chen</u>																																					
Signature: <u>CAROL CHEN</u> Digitally signed by CAROL CHEN Date: 2024.12.10 18:09:32 -05'00'																																					
UIC Inspector																																					
Name: _____																																					
Signature: _____																																					
Version 2018-04-18																																					

Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	4	6
	Year-Month-Day:	2	0	2	4	-	1	0	-	2	2
	EPA Permit # (or RA):	R	A								
					Page	2		Of		2	

[illegible]

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID: RIMG0190 Time: 11:14 am Lat (°N): 37.77837 Long (°W): -83.01039

Description: injection well

Photo ID: RIMG0191 Time: 11:14 am Lat (°N): 37.778878 Long (°W): -83.010483

Description: injection well, different angle

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____