

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	1	7
Year-Month-Day:						2	0	2	3	-	0	3	-	3	0	
EPA Permit # (or RA):						N	O	N	E							
						Page	1	Of	2							
Inspector(s): Carl E. Weller (lead), Carol Chen Start Time: 1:18 pm																
End Time: 1:28 pm																
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)															
	Street Address: 5415 Oil Plant Rd															
	City: Jay County: Santa Rosa State: FL Zip: 32565															
	Nature of Business: oil and gas production															
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702															
	Email:															
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319															
	O/O Mailing Address: 5415 Oil Plant Rd															
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565															
	Well Name & #: Rosie L. Kersey #10-3 API No. 0911320040 PA No. 311588															
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_522															
	Latitude (°N): 30.9581754 Longitude (°W): -87.16654472 Elevation (ft): Top packer BHA															
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing Otis WB @ 15257'															
	PBTD: 15754' ☐ Other: surface casing 10¾" at 3678' Bottom Packer BHA Arrowdrill B															
	Total Depth (ft): 15811' Inner Casing Size (in): Tubing Size (in): Packer Depth (ft): 15112'															
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15469' Bottom(ft): 15646' Max. Injection Pressure (psig): 7500 N₂ psi															
Field Measurements and Observations	Latitude (°N): 30.95824 Longitude (°W): -87.16650 Elevation (ft):															
	EPA GPS ID: SX8123 Well Status (see table): AC If not Active, Reported Date Last Active:															
	Nature of Injected Fluid(s) if any: Nitrogen (N₂) injection															
	General Condition of the Well Site:															
	Additional Notes & Comments: maximum injection pressures are N₂ 7500 psi, Produced Water (PW) 4400 psi															
	Notes & Comments (include discrepancies from database values): The T-disk was not installed on the Nitrogen (N₂) flowline															
	Perforations (Smackover Formation): and the line itself feels cold, clearly showing gas injection.															
	15469' to 15489' (GR-4SPF) 3/09/1974 T-disk was installed on the PW flowline, blocking injection.															
	15489' to 15527' (GR-4SPF) 11/14/2012 Tubing gauge: 5000 psi															
	15527' to 15547' (GR-4SPF) 3/09/1974 Production gauge 0 psi															
	15547 to 15586' (GR-4SPF) 11/14/2012 Surface gauge: 0 psi															
	15586' to 15646' (GR-4SPF) 5/04/1972 Injection well passed a mechanical integrity test on 5/12/2022.															
See reverse for additional observations, comments and photo log																
UIC Inspector								UIC Inspector								
Name: Carl E. Weller								Name: Carol Chen								
Signature: CARL WELLER (Affiliate)								Signature: CAROL CHEN								
Digitally signed by CARL WELLER (Affiliate) Date: 2023.05.23 15:07:57 -04'00'								Digitally signed by CAROL CHEN Date: 2023.05.17 13:59:44 -04'00'								
Version 2018-04-18																

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID EPA Well ID#: F L S 1 1 3 0 0 1 7 Year-Month-Day: 2 0 2 3 - 0 3 - 3 0 EPA Permit # (or RA): N O N E Page 2 Of 2												
Field Measurements and Observations (Cont.) (Cont)																	
Photo Log Photographer: Carl E. Weller EPA Camera ID: SX8123 Photo ID: 206 Time: 1:18 pm Lat (°N): 30.95836 Long (°W) -87.16708 Description: sign posted to identify the injection well Photo ID: 207 Time: 1:20 pm Lat (°N): 30.95824 Long (°W) -87.16650 Description: close-up photo of the injection well Photo ID: Time: Lat (°N): Long (°W) Description: Photo ID: Time: Lat (°N): Long (°W) Description: Photo ID: Time: Lat (°N): Long (°W) Description: Photo ID: Time: Lat (°N): Long (°W) Description:																	
UIC Inspector Name: Carl E. Weller Signature: CARL WELLER (Affiliate) Digitally signed by CARL WELLER (Affiliate) Date: 2023.05.23 15:08:26 -04'00'									UIC Inspector Name: Carol Chen Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2023.05.17 14:00:14 -04'00'								
Version 2018-04-18																	