

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/05/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	The Long Trusts	
Facility Name:	Mary Smith	
Facility Physical Location:	32.267637, -94.907623	
(city, state, zip code)	Overton, Texas 75684	
Mailing address:	P.O. Box 921	
(city, state, zip code)	Kilgore, Texas 75663	
County/Parish:	Rusk County	
Facility Phone Number	903-984-3443	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011261	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited The Long Trusts oil and gas facility located near Overton, Texas on 03/05/2020 for an unannounced inspection. There were no representatives of The Long Trusts present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Mary Smith and has state identification number: RRC No. 08568.

Section II - OBSERVATIONS

I observed that the produced water (brine) pump and gas separator were located outside the secondary containment area. A drainpipe and plug were observed in the secondary containment and the drain valve was open during the inspection. I did not observe any surface damage outside of the secondary containment call.

Section III – AREAS OF CONCERN

The secondary containment area had a drainpipe with a valve that was open during the inspection.

Section IV – FOLLOW UP

EPA water enforcement will refer this to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A