

Monsanto

FROM ANNISTON, ALABAMA

cc:

L. L. Faulkner
V. R. Haupt
J. C. Landwehr
W. B. Papageorge
H. L. Williams

August 20, 1968

SUBJECT CEA 1430 - 1452 - 1892

REFERENCE

TO Mr. W. A. Kuhn

General Offices

These photos taken August 16, 1968, illustrate progress over the past five working days (except for 1892 which is the first picture you've seen of this area).

- Photo 1: Looks east - across Duncan and down 6th Street toward the truck loading area curb is about 50% poured. As you can barely see, almost six bays of roof have been laid on the west side of the Warehouse.
- Photo 2: Looks south. Curbing and dock outline the Aroclor tank truck loading pad (yet to be paved). What appears to be holes in the Warehouse roof are really translucent plastic panels for skylights.
- Photo 3: Looks north from the third floor of Building 28. The extent of roofing progress is obvious.
- Photo 4: Looks northwest from the third floor of Building 28. About the only evidence of change here is the beginning of the retaining wall form along the railroad track, barely visible next to the pipe bridge support, lower righthand corner. The truck is on his way to unload at the new stores receiving dock.
- Photo 5: Looks northeast over the sight of the new 300 M gallon benzene storage tank. The large vertical tank on the right is the 200 M gallon refined Biphenyl storage. The tank immediately to its left is the present benzene storage tank (50 M gallon). The next two tanks (horizontal) are the benzene feed tanks. The piles of dirt along the temporary dirt dike wall at the Biphenyl tank are from the excavation for the footer for the concrete dike around the benzene tanks.

W. F. Taffee

WFT:kd
Enclosures

0354014

TOWOLDMON0044660