

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	05/30/2024	Time	18:15
		Operator Representative	John P. Long, Jr.		
Operator Info	John P. Long, Jr. 9226 Okesa Road Bartlesville, OK 74003 Phone: 918-625-7282	Inventory ID	OS4070000		
		API Well No			
		Lease Name	OKLAHOMA LAND & CATTLE		
		Well ID	2-S		
Location	SW 23 26N 09E	Status	Inactive	Well Type	Disposal
Latitude	36.71015	Longitude	-96.30613		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	John P. Long, Jr.		
Inspect No.		Date Last MIT	08/06/2015	Last Test Result	Fail
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 656
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	At the time of the inspection well OS4070000 was disconnected and not injecting but had tubing, changeover and cutoff valve installed. There was no production equipment or infrastructure present on the well location. The well did not appear to have been converted to production and was not being used for production at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.71015, -96.30613		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010445

Orientation: N

Date of Photo: 5/30/2024

Time of Photo: 6:14 PM

Latitude: 36.71015

Longitude: -96.30613

Photographer: Matthew Allen

Description: This was well OS4070000 at the time of the inspection. There was no production equipment installed on the well. The well had tubing, changeover and cutoff valve installed.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.71015, -96.30613		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010446

Orientation: N

Date of Photo: 5/30/2024

Time of Photo: 6:18 PM

Latitude: 36.71015

Longitude: -96.30613

Photographer: Matthew Allen

Description: Well, OS4070000 was in the foreground of the photo and a production well on the same location can be seen approximately 65 feet to the north.