

INDUSTRIAL HYGIENE SAMPLE RECORD FORM

Westinghouse Electric Corp
5100 Bandrock Ave
East Rah Pa. 15112
 (CITY) (STATE) (ZIP)

10707

CORP. I. H. NUMBER
 SITE REPRESENTATIVE Bob Selembo
 PHONE NUMBER (WIN) 299-5442

SAMPLING DESCRIPTION

*** COMPLETE THIS SECTION AND RETAIN. (SEND A COPY TO CORPORATE INDUSTRIAL HYGIENE**

EMPLOYEE NAME Bulk Sample SAMPLE DATE: 9/30/85
 SOCIAL SECURITY NUMBER _____ JOB TITLE _____

DESCRIPTION OF WORK _____

DEPARTMENT LRA COLUMN NUMBER _____

SECTION D-5 (Super. Bill Flannigan) BUILDING _____

SAMPLED BY Bob Selembo SAMPLE ZONE _____

PUMP / DOSIMETER # _____ CALIBRATION DATE ____/____/____

FLOW RATE _____ LITERS OR MLITERS _____ PER MINUTE NOISE THRESHOLD _____

FIRST STARTING TIME ____:____ FIRST STOPPING TIME ____:____ TOTAL TIME ____ MIN

NEW STARTING TIME ____:____ SECOND STOPPING TIME ____:____ VOLUME ____ LITERS

TYPE OF COLLECTING DEVICE _____

DEVICE NUMBER _____

PLAINTIFF'S
EXHIBIT
WH-1004

WERE PROTECTIVE DEVICES USED? _____

TYPE OF EAR PLUGS..... - _____

TYPE OF EAR MUFFS..... - _____

TYPE OF GLOVES..... - _____

NIOSH RESP. APPROVAL #... - _____

OTHER..... - _____

ANALYSIS REQUESTED (SPECIFY CONTAMINANT(S)): Asbestos

FINAL REMARKS: Bulk Sample of material that was weighed
above 50 pounds of material sent to
Clayton Lab to determine if the material is or
contains asbestos. Bob Selembo Safety Dept

PLEASE CONTACT THE FOLLOWING INDIVIDUAL WHEN ADDITIONAL SAMPLES ARE NEEDED OR QUESTIONS ON ANALYSES ARISE: Robert Lieckfield, Manager, Laboratory Services, Clayton Environmental Consultants, Inc. Phone: (313) 424-8860.

IF QUESTIONS ON INTERPRETATION OF RESULTS ARISE, PLEASE CALL CORPORATE INDUSTRIAL HYGIENE - WIN 236-1364 or BELL (412) 256-1364.

Mark A. Perriello, CIH
Senior Industrial Hygiene Engineer

RY 16, 1985

- OVER -

6005881 See attch

Clayton Environmental Consultants, Inc.
25711 Southfield Road
Southfield, Michigan 48075
Telephone (313) 424-8860

LABORATORY REQUEST

Name: Robert C. Selembo Title: Administration Safety

Company: WESTINGHOUSE ELECTRIC CORPORATION

Street: 700 Braddock Avenue

City: East Pittsburgh State: PA Zip: 15112

Phone: (412) 829-5442 Client P.O. No. Please Bill to the above
Safety Dept

Sampling Date: Bulk Sample Sampling Media: — Bob Selembo
4610

Sample Description	Air Volume (give units)	Analyses Requested
1 <u>Please analyze enclosed</u>		
2 <u>Bulk Sample for Asbestos</u>		
3		
4		
5		
6 <u>Material is wrapping from journals</u>		
7 <u>of rotor sent to us for repair from custom</u>		
8		
9 <u>Does it contain or is it asbestos</u>		
10		
11		
12		
13		

Special Instructions (method, limit of detection) Please rush
and call back results by 10/8/85 Thank You

Send copy of all reports to Mr. Mark Perriello, Pittsburgh, PA.

Signature: Robert C. Selembo Date: 9/30/85

LAB USE ONLY	Date rec'd:
	Job No.: <u>844 6005882</u>
	Log-in Date: _____

010384

55005374

CLAYTON ENVIRONMENTAL CONSULTANTS, INC.

Analytical Laboratory Report

Mr. Robert C. Selembo

Safety Department, 4G-10

WESTINGHOUSE ELECTRIC CORPORATION

700 Braddock Avenue

East Pittsburgh, PA 15112

Date Reported: 11-OCT-85
Date Received: 07-OCT-85
Clayton Job No.: 29377-17

Dear Mr. Selembo:

The sample which you submitted to us has been analyzed as requested; the result is compiled in the following table.

Lab Number	Sample Description	Non-Asbestos	
		Asbestos Identification	Fibrous Materials
418749	BULK; gray fiber and filler mixture, compressed	~45% chrysotile	no fibers detected

Analysis performed in accordance with EPA protocol for asbestos using polarized light microscopy (PLM).

Please contact us at (313) 424-8860 if you have any questions. It has been a pleasure assisting you.


Robert Lieckfield Jr., C.I.H.
Manager, Laboratory Services
Southfield Office

cc: Mr. Mark Perriello ✓

844 6005883