

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/27/2024	Time	14:00
Inspection Due	2021-08-25T00:00:00Z	Operator Representative	4D Oil & Gas, LLC		
Operator Info	4D Oil & Gas, LLC 532 Kihekah Pawhuska, OK 74056 Phone: 580-541-5802	Inventory ID	OS5800000		
		API Well No			
		Lease Name	Heard		
		Well ID	1A		
Location	NW 29 26N 11E	Status	Active	Well Type	Disposal
Latitude	36.707688	Longitude	-96.142757		
Inspection Reason	Emergency Response Complaint Response	Responsible Company at Time of Inspection	4D Oil & Gas, LLC		
Inspect No.		Date Last MIT	12/22/2017	Last Test Result	Acceptable
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubing s		Annulus	
Monitoring Device		Fittings	N	N	Max Pressure 547
FLM Canister Pressure		Actual Pressure	25	0	Max Volume 22500
Lease Status	Active	Determined?	Company Gage	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	Well OS5800000 was connected and injecting at the time of the inspection. The tubing was observed with 25 in.Hg vacuum and the annulus was observed with 0psi through an open valve. There were no areas of concern at the time of the inspection.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2024.03.19 11:49:23 -05'00'				
Supervisor Signature	ENOCH JOHNBULL Digitally signed by ENOCH JOHNBULL Date: 2024.03.19 13:49:56 -05'00'				

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.707688, -96.142757		
City: Okesa	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_078

Orientation: N/A

Date of Photo: 02/27/2024

Time of Photo: 2:01 PM

Latitude: 36.707688

Longitude: -96.142757

Photographer: Matthew Allen

Description: This was the well sign for well OS5800000.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.707688, -96.142757		
City: Okesa	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0079

Orientation: W

Date of Photo: 02/27/2024

Time of Photo: 2:02 PM

Latitude: 36.707688

Longitude: -96.142757

Photographer: Matthew Allen

Description: This was well OS5800000, connected and injecting at the time of the inspection.