

1. Contract Identification

File No.: 9713 File Name: GATX (Repair Air Leaks)

Location(s): Masury, Ohio

Work Description: Repair air leaks; seal all ductwork at
Housing to eliminate air leaks

Dates: (1) General: 7/13/83 - 8/1/83
(2) Specific (on-site): _____

Amount: \$1030.60

Contractor: GATX

Reviewer: WRW

Date: 12/26/89

Location/Work Description Cont': _____

PLAINTIFF'S EXHIBIT

TAS-85

III. Employees

A. Employees/Workers

B. Days worked

