

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	5	3
Year-Month-Day:					2	0	2	4	-	1	0	-	2	2	
EPA Permit # (or RA):					R	A									
					Page	1	Of	2							
Inspector(s): Carol Chen (lead), Lonnie Dorn Start Time: 12:07 pm															
End Time: 12:10 am															
Facility Contact Information	Facility Name: Slone Energy, LLC														
	Street Address: 8966 KY RT 40 West, P.O. Box 220														
	City: Oil Springs County: Magoffin State: KY Zip: 41238														
	Nature of Business: oil production														
	Facility Owner/Operator: Mr. S. Chris Slone, PE Phone: 606.297.5330 work														
	Email: chrisslone@sloneenergy.com														
	Facility Contact (if different): Phone: 606.225.2206 cell														
	O/O Mailing Address:														
	City: County: State: Zip:														
	Well Data from File	Well Name & #: JACK HUNLEY #W-24													
Well Type (see table): Class II-R, Enhanced Oil Recovery (EOR) State Permit:															
Latitude (°N): 37.82164 Longitude (°W): -83.03403 Elevation (ft):															
Injection Method (check applicable): ☐ Casing Injector; ☐ Tubing & Packer; ☐ Cemented Injection Tubing															
☐ Other: 6 5/8"															
Total Depth (ft): Inner Casing Size (in): 2 3/8" Tubing Size (in): 1" Packer Depth (ft):															
Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):															
Field Measurements and Observations	Latitude (°N): 37.821693 Longitude (°W): -83.034038 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): TA If not Active, Reported Date Last Active: unknown														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	The injection well is disconnected from the injection line. The wellcap shows some corrosion.														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.12.11 11:15:00 -05'00'															
Version 2018-04-18															

Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	5	3
	Year-Month-Day:	2	0	2	4	-	1	0	-	2	2
	EPA Permit # (or RA):	R	A								
Page							2	Of	2		

Field Measurements and Observations (Cont.)

JACK HUNLEY #W-24

Class II-R, Enhanced Oil Recovery (EOR)

Photo Log

Photo ID: RIMG0197 Time: 12:08 pm Lat (°N): 37.821728 Long (°W) -83.034105

Description: injection well

Photo ID: RIMG0198 Time: 12:08 pm Lat (°N): 37.821693 Long (°W): -83.034038

Description: injection well, slightly closer

Photo ID: RIMG0199 Time: 12:09 pm Lat (°N): 37.821756 Long (°W): -83.033963

Description: injection well, farther back

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description:

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description:

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Photo ID: _____ Name: _____ Lat (N): _____ Long (W): _____

Description: _____

UIC Inspector

Name: Carol Chen

Name: _____

Signature: CAROL CHEN

Digitally signed by CAROL CHEN
Date: 2024.12.11 11:15:22 -05'00'

Signature: _____