

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 1 4											
						Year-Month-Day: 2 0 2 4 - 0 4 - 3 0											
						EPA Permit # (or RA):											
						Page 1 Of 2											
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 1:40 pm																	
End Time: 1:48 pm																	
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)																
	Street Address: 5415 Oil Plant Rd																
	City: Jay County: Santa Rosa State: FL Zip: 32565																
	Nature of Business: oil and gas production																
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702																
	Email:																
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319																
	O/O Mailing Address: 5415 Oil Plant Rd																
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565																
	Well Name & #: McDavid Lands Etal #7-3 API No. 0911320025 PA No. 311581																
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_496																
	Latitude (°N): 30.977056 Longitude (°W): -87.180028 Elevation (ft):																
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing																
	PBTD: 15,592' ☐ Other:																
	Smackover Formation 3 sets perforations																
	Total Depth (ft): 15,846' Inner Casing Size (in): 8 3/4" Tubing Size (in): 4 1/2" Packer Depth (ft): 15,067'																
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15,480' Bottom(ft) 15,540' Max. Injection Pressure (psig): 7,500 psi gas N2 4,400psi PW																
	Latitude (°N): 30.977195 Longitude (°W): -87.179982 Elevation (ft):																
	EPA GPS ID: S75532 Well Status (see table): AC If not Active, Reported Date Last Active:																
	Nature of Injected Fluid(s) if any: Produced Waters (PW)																
	General Condition of the Well Site:																
	Notes & Comments (include discrepancies from database values):																
	DANGER sign posted: H2S May Be Present..Authorized Personnel Only..Hazardous Operations..Keep Out...																
	This well is actively injecting produced fluids. The produced fluids manifold is close to a wooded																
	area. An elongated pooling of fluids is observed Tubing gauge: 1800 psi																
	directly in front of the manifold upon sandy soil, Production gauge: 0 psi																
between the injection well and manifold. Surface gauge: 0 psi																	
Flowline gauge:																	
See reverse for additional observations, comments and photo log																	
UIC Inspector								UIC Inspector									
Name: Carol Chen								Name:									
Signature: CAROL CHEN								Signature:									
Digitally signed by CAROL CHEN Date: 2024.07.09 10:36:31 -04'00'																	
Version 2018-04-18																	

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	1	4
	Year-Month-Day:	2	0	2	4	-	0	4	-	3	0
	EPA Permit # (or RA):										
								Page	2	Of	2

[illegible]

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID: RIMG00131 Time: 1:40 pm Lat (°N): 30.977087 Long (°W) -87.180005

Description: Photo of the injection well, sign with well identification, and DANGER sign: H₂S May Be Present...

Photo ID: RIMG00132 Time: 1:43 pm Lat (°N): 30.977195 Long (°W) -87.179982

Description: surface pressure gauge reads 0 psi

Photo ID: RIMG00133 Time: 1:44 pm Lat (°N): 30.977195 Long (°W) -87.179998

Description: annulus pressure gauge reads 0 psi

Photo ID: RIMG00134 Time: 1:45 pm Lat (°N): 30.977107 Long (°W) -87.180086

Description: injection tubing gauge reads 1800 psi

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector

Name: _____

Signature: _____