

INSPECTION REPORT
Facility Name: Fast Lane Holdings

Attached please find the United States Environmental Protection Agency's (EPA's) inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to a Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Number:	3601757526-2024
Inspection Date(s):	December 12, 2024
Regulatory Program(s):	Clean Air Act Title II – Mobile Source
EPA Region/Program Conducting Inspection:	Region 4 Air Enforcement Branch
Company Name:	Fast Lane Holdings
Facility Name:	Fast Lane Truck Repair; Fast Lane Carriers
Facility Street Address:	115 Bain Drive
Facility City, State, Zip Code:	La Vergne, Tennessee 37086

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Supervisor Approval			
<u>Carrie Griffith</u> Field Inspector Name	<u>CARRIE GRIFFITH</u> Field Inspector Signature	<u>Digitally signed by CARRIE GRIFFITH Date: 2025.02.11 07:40:14 -05'00'</u>	_____ Date
<u>Todd Groendyke</u> Name of Approving Official	<u>Chief, SAES</u> Title	<u>TODD GROENDYKE</u> Approving Official Signature	<u>Digitally signed by TODD GROENDYKE Date: 2025.02.11 09:13:15 -05'00'</u> _____ Date

INSPECTION REPORT

Facility Name: Fast Lane Holdings

General Inspection Information			
Inspector(s):	Carrie Griffith, Loriany Rivera	Arrival Date/Time:	12/12/2024 9:08 CST
Primary Facility Representative & Title:	Mirsad Mehinovic	Departure Date/Time:	12/12/2024 12:53 CST
Facility Contact Phone/Email:	615-314-3268 mirsad.m@fastlaneco.com	Compliance Assistance Reference Materials Provided to Facility:	☒ SBREFA Form ☒ EPA Enforcement Alert ☐ EPA Tampering Policy ☐ Copy of CAA § 203(a)(3) ☐ Copy of CAA § 114 ☐ §208/§114 Preservation Letter ☒ Discussion of Right to Claim CBI ☐ Other:
Time Inspector(s) Presented Credentials:	9:19 CST		
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	Yes - Senad Becic, Owner, consented to the inspection during the opening meeting.		
Photograph Range:	0055 - 0063	Photographer Name:	Griffith
Notes:	Fast Lane Holdings, owned solely by Senad Becic, is the parent company of Fast Lane Carriers, a freight transportation company, and Fast Lane Truck Repair, a diesel vehicle repair shop. Fast Lane Carriers began operating in 2014, and Fast Lane Truck Repair opened in approximately 2019. Both companies operate out of the same single location.		

Facility Business Activities			
Type(s) of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufacturing		
☐	Retail		
☒	Service Shop	Shop performs all kinds of work, including major repairs, except for ECM programming.	Shop does all work on fleet vehicles and services approximately 5 non-company vehicles per week
☒	Fleet	There are 38 vehicles in the fleet: 27 owned by Fast Lane Carriers and 11 by owner/operators. Fleet vehicles are model year 2015 and newer.	Short-haul trucking; trucks return every other day.
☐	Other		
Notes		EPA inspectors observed the check engine light illuminated for several fleet vehicles. Facility personnel said this was caused by their electronic logging device connected to the battery.	

INSPECTION REPORT

Facility Name: Fast Lane Holdings

Personnel Interviewed			
Name	Title	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Mirsad Mehinovic	Safety Manager	615-314-3268 mirsad.m@fastlaneco.com	Griffith
Zijad Becic	General Manager	n/a	Griffith

Documents Requested		
Document Requested	Status	Notes/Comments
All work orders and service invoices from June 2024 to December 2024.	☒ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	Inspectors reviewed electronic records onsite.
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	

Vehicles Inspected/Observed				
VIN (last 8 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Scan Conducted? (Yes/No)	Observations
KN903870	KVPT2TRAC900	No	Yes	Check engine light on.
NN290715	MVPT2TRAC900	No	Yes	Check engine light on.
NN296606	MVPT2TRAC900	No	Yes	No photos taken. Check engine light on.
GDGW4611	GDTN2TRAC13C	No	Yes	No photos taken.
HN979934	HVPT2TRAC900	No	Yes	No photos taken. Check engine light on.
FN920407	FVPT2TRAC900	No	Yes	No photos taken.

PHOTOGRAPH LOG**Fast Lane Holdings**

Image Number	File Name	Date	Time (CST)	Description of Image
1	PC120055	12/12/2024	9:35	Vehicle 1 - front
2	PC120056	12/12/2024	9:35	Vehicle 1 – side
3	PC120057	12/12/2024	9:35	Vehicle 1 – label
4	PC120058	12/12/2024	9:36	Vehicle 1 – side
5	PC120059	12/12/2024	9:37	Vehicle 1 – side
6	PC120060	12/12/2024	9:40	Vehicle 1 – dashboard
7	PC120061	12/12/2024	9:51	Vehicle 2 – front
8	PC120062	12/12/2024	9:52	Vehicle 2 – label
9	PC120063	12/12/2024	9:53	Vehicle 2 - dashboard

Photographs were taken by EPA inspector Carrie Griffith.