



ARCHITECT 90
The Value of a Lifetime

August 21, 1987

Mr. John McCauley
The Commonwealth of Mass.
D. E. Q. E.
5 Commonwealth Avenue
Woburn, MA 01801-1009

Dear John,

Enclosed are copies of all shipping sheets for the asbestos removed from our Norwood plant during cleanup activities. To date there have been seven (7) loads removed which have been delivered to Sawyer Environ, Hamden, Maine. Also enclosed are copies of the various bulk and air samples taken during the cleanup activities conducted by Marlyn. There are more air sample reports that have yet to come back from the lab and we will forward those to you when we receive them.


As we discussed during your last visit, the next steps in this cleanup process are:

1. Make a final inspection of the tank farm area so demolition could begin.
2. Formulate strategies and plan for a tank farm demolition time table as well as the remaining asbestos clean up and other building demolition activities that will follow.

Marylyn believes the tank farm is ready for your inspection and we have some information ready for your review concerning demolition activities and scheduling.

Since you are on vacation this week and I will be out next week, I would ask that you schedule your next visit for either the week of August 30th or September 8th.

Sincerely,


John F. Hardy
Manufacturing Manager

JFH/em

Encl.

cc: J. Carr

004189