

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	0	9	9	0	0	0	5
Year-Month-Day:					2	0	2	4	-	0	2	-	2	1	
EPA Permit # (or RA):					K	Y	I	0	5	9	0				
					Page	1		Of	2						
Inspector(s): Carol Chen (lead), Brianna LaPapa Start Time: 10:04 am															
End Time: 10:08 am															
Facility Contact Information	Facility Name: Logsdon Valley Oil Co., Inc.														
	Street Address: 105 Bedford Court														
	City: Horse Cave County: Hart State: KY Zip: 42749														
	Nature of Business: Oil and gas extraction														
	Facility Owner/Operator: Logsdon Valley Oil Co., Inc. Phone: 270-537-4288														
	Email: estinson@scrtc.com														
	Facility Contact (if different): Ellen Stinson, President Phone: 270-537-4288														
	O/O Mailing Address: 105 Bedford Court														
	City: Horse Cave County: Hart State: KY Zip: 42749														
Well Data from File	Well Name & #: Carter & Chaney #VA-2														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: 36471														
	Latitude (°N): 37.18339 Longitude (°W): -85.78526 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: ☐ Other:														
	Total Depth (ft): 625' Inner Casing Size (in): 4½" to 625' Tubing Size (in): 2⅜" Packer Depth (ft):														
	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
Field Measurements and Observations	Latitude (°N): 37.183473 Longitude (°W): -85.785227 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): PA If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	Well is plugged, but 4½" casing at surface was not removed.														
	Injection well is viewed within a large cement pad, several feet in diameter.														
See reverse for additional observations, comments and photo log															
UIC Inspector Name: Carol Chen								UIC Inspector Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.03.27 18:52:48 -04'00'								Signature:							
Version 2018-04-18															

Inspection ID	EPA Well ID#:	K	Y	S	0	9	9	0	0	0	5
	Year-Month-Day:	2	0	2	4	-	0	2	-	2	1
	EPA Permit # (or RA):	K	Y	I	0	5	9	0			
Page						2		Of		2	

Photo Log

Photographer: Brianna LaPapa EPA Camera ID: S75332

Photo ID: RIMG0031 Time: 10:07 am Lat (°N): 37.183967 Long (°W): -85.783172

Description: injection well casing, within cement pad

Photo ID: RIMG0032 Time: 10:07 am Lat (°N): 37.183473 Long (°W): -85.785227

Description: closer look of injection well casing, covered in cement

Photo ID: RIMG0033 Time: 10:08 am Lat (°N): 37.183407 Long (°W): -85.785177

Description: injection well casing, within cement pad

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Version 2018-04-18