

FILE NAME: Allied Signal Bendix (ASB)

DATE: 1979 Jan 5

DOC#: ASB093

DOCUMENT DESCRIPTION: Memo RE Results of Asbestos Air Monitoring
Nov 1978

Internal
Memorandum

Bendix

Executive Offices
Southfield, Michigan

Date January 5, 1979
To Gordon Detenbeck
From Ben Wong
Subject Results of asbestos air monitoring - November 14, 15, 1978

Letter No.

REPRODUCED FROM
THE COLLECTIONS OF
THE BUREAU OF
LABOR & URBAN AFFAIRS
UNIVERSITY MICROFILMS

Outlined in the following are the results of the air monitoring conducted for asbestos along with a comparison of previous sampling results. The results show that exposure concentration has remained insignificant from both an occupational health and legal viewpoint. As always please retain the results for documentation purposes.

The majority of samples are breathing zone samples which is most indicative of employee exposure. It is cautioned that area samples, because they are not mobile like the employee, are indicative of contamination sources only and not personal exposure.

Overall housekeeping in the asbestos areas was noted to be good. However, the one problem area remains to be the bagging enclosure area of the dust collector. Accumulations of asbestos dust was still noted and it was learned that outside contractor bag house cleaning operators were not equipped with proper personal protective gear. It is extremely important, from liability aspect, that the dust collector area is as free of asbestos accumulations as possible and that dust collector cleaning operators are equipped with proper protective gear.

AREA OR OPERATION

<u>Prince Road Plant</u>	<u>June 26, 28, 1978</u>	<u>November 14, 15, 1978</u>
Pack & Inspection, Hand line (S. Zaus)	.21 f/cc	.064 f/cc (S. Kawa)
1st Shoe Assembler, Hand line (J. Trisan)	.28 f/cc	-
Stockman, Hand line (Z. Duchnowski)	.06 f/cc	refused to be sampled
2nd Shoe Assembler, Hand line (S. Lustig)	.10 f/cc	.017 f/cc (D. Piper)
Pin & Lever, Hand line (P. Brunett)	.09 f/cc	.11 f/cc (G. Verkie)

PERIOD 800-631-8888

PLAINTIFF'S
EXHIBIT

758

internal
Memorandum



Date January 5, 1979 Letter No.

Page -2-

Prince Road Plant (continued)

Second Holddown	-	.013 f/cc (J. Renand)
-----------------	---	--------------------------

Area Sample 15' behind shoe & lever	-	.018 f/cc
--	---	-----------

Argyle Road Plant

Grinder, Line #1 (M. Bryant)	.14 f/cc	.024 f/cc (C. Guiseppe)
---------------------------------	----------	----------------------------

Grinder, Line #4 (C. Scandale)	.15 f/cc	Not operating
-----------------------------------	----------	---------------

Grinder, Line #2 (F. Bonofiglio)	.10 f/cc	Not operating
-------------------------------------	----------	---------------

Inspection, Lines #3 & #4 (J. McCann, A. Tortola)	.07 f/cc	-
--	----------	---

Riveter, Line #5 (J. Pisani)	.10 f/cc	.24 f/cc (D. Jacques)
---------------------------------	----------	--------------------------

Sweeper (S. Moroz)	.03 f/cc	-
-----------------------	----------	---

Repair and Rework (M. Kajan)	.12 f/cc	.44 f/cc (M. Jezom)
---------------------------------	----------	------------------------

Drilling (M. Bryant)	.10 f/cc	.22 f/cc (J. Marra)
-------------------------	----------	------------------------

Stockman (N. Nadon)	-	.039 f/cc
------------------------	---	-----------

Inspection Line #1 (P. Dunn)	-	.018 f/cc
---------------------------------	---	-----------

Area Sample, top of auto drill control panel	-	.025 f/cc
---	---	-----------

Internal
Memorandum



Date January 5, 1979 Letter No.

Page -3-

Argyle Road Plant (continued)

Area Sample, outdoor dust collector .04 f/cc .26 f/cc

A large, handwritten signature in black ink, appearing to be "B. W. J." with a stylized flourish at the end.

BW/af

cc: R. M. Robbins
T. C. Schaefer