



Clean Air Act Compliance Inspection Report

United States Environmental Protection Agency
Region 10 – Seattle, WA

Partial Compliance Evaluation

Pace International

**Yakama Nation Reservation
Wapato, Washington**

Inspection Date: August 10, 2023

Report Author Signature

Date

Zach Hedgpeth, PE
Environmental Engineer
EPA Region 10

Peer Review Signature

Date

Philip Myers, PhD, PE
Mechanical Engineer
EPA-NEIC

Manager Signature

Date

Justin Spenillo
Acting Supervisor, Air & Toxics Enforcement Section
EPA Region 10

Table of Contents

1. Basic Facility and Inspection Information.....	3
2. Introduction	4
3. Inspection Elements and Field Observations – August 10, 2023	4
4. Closing Conference	4

Attachments

Attachment 1	GMAP Technical Information
Attachment 2	GMAP Data

1. Basic Facility and Inspection Information

Facility: Pace International, LLC
Yakama Nation Reservation
5661 Branch Road
Wapato, WA 98951

Mailing Address: Same

FRS Number: 110070747322

Facility Contacts: Chris Heintzman – Senior Operations Manager
925-357-6781, christine.heintzman@paceint.com

Josh Peters – EHS Specialist

Agency Inspectors: Zach Hedgpeth, PE – EPA Region 10
206-553-1217, hedgpeth.zach@epa.gov

Agency Staff: Philip Myers, PhD, PE – EPA NEIC
303-462-9301, myers.philip@epa.gov

Yakama Nation Reps: Terry Ganuelas
Air Quality Technician
Yakama Nation Environmental Management Program

Katie Swan
Air Quality Specialist
Yakama Nation Environmental Management Program

Inspection: August 10, 2023
Inspection Report: March 25, 2024

Inspection Notice: Announced

Disclaimer

This report is a summary of observations and information gathered from the facility at the time of the inspection. The information provided does not constitute a final decision regarding compliance with the Clean Air Act (CAA) and applicable regulations or permits, nor is it meant to be a comprehensive report of all activities and processes conducted at the facility.

2. Introduction

- a) The primary purpose of this inspection was to collect onsite pollutant measurements of the outside air using the Geospatial Measurement of Air Pollution (GMAP) vehicle-mounted instruments. Elizabeth Sanchez, the Program Manager for the Yakama Nation Environmental Management Program, was made aware of the inspection beforehand and Terry Ganuelas, Air Quality Technician, and Katie Swan, Air Quality Specialist, of Yakama Nation participated in the inspection.
- b) Mr. Ganuelas had called in advance to provide notice and coordinate the GMAP inspection with the facility.

3. Inspection Elements and Field Observations – August 10, 2023

- a) We arrived at the facility around 11:06 and met Ms. Heintzman and Mr. Peters at the facility office.
- b) Opening Conference – The opening conference was held informally in the facility office. We explained the purpose of the inspection as described above, and I presented my inspector credentials.
- c) GMAP Mapping – Following the opening discussion, we returned to the GMAP vehicle in the facility parking lot. Mr. Peters joined us in the vehicle during mapping, and Dr. Myers provided an explanation of the pollutant and geospatial measurement capabilities of the equipment. No concentrations notably higher than background were detected for any pollutants during mapping onsite at the facility. Concentrations of benzene above background were detected while the GMAP vehicle idled near the entrance gate of the facility upon arrival. The data collected by the GMAP vehicle is included as Attachment 2 to this report, and consists of a .kml mapping file which can be opened using Google Earth to show the measurement results visually.

4. Closing Conference

- a) A closing discussion occurred in the facility office with Ms. Heintzman and Mr. Peters as well as Terry Ganuelas and Katie Swan following the conclusion of mapping activities.
- b) I provided a brief overview of the EPA Region 10 compliance and enforcement process and discussed the timeline for issuance of the inspection report.

We departed the facility at around 12:15 following the closing discussion.