

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	05/09/2024	
Media Program:	Water (CWA)	
Regulatory Program(s)	Water (CWA) Brine Program (Oil & Gas inspection)	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	Flowline spill (off oil lease road off All Gulf Rd)	
Facility Physical Location:	Off oil lease road off All Gulf Rd in Smackover at 33.339567, -92.687617	
(city, state, zip code)	Smackover, AR 71762	
Mailing address:	100 East 7th Street	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry Langley jloc58@yahoo.com	Owner / Operator
FRS Number:	N/A	
Identification/Permit Number:	ARU002230	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Kerri McCabe (lead)	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Michael Blaha	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Kerri McCabe	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Kerri McCabe (lead) and Michael Blaha arrived at the Jerry Langley Oil Co., LLC / Flowline Release, located off an oil lease road off All Gulf Road at 33.339567, -92.687617; at 1242 on 05/09/2024 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted a follow-up inspection on the Jerry Langley Oil Co., LLC / Flowline Release, which was a release of crude oil and saltwater onto the ground as a result of a broken coupling on a flowline.

Section II - OBSERVATIONS

I observed the area of the release of crude oil and saltwater from a broken coupling on a flowline noted in the 03/14/2024 inspection. The broken coupling had been repaired the same day it was reported; however, cleanup was pending. I observed the area had been remediated with sand application, see Appendix 1 (Photograph Log), Photo No. 1. For additional GPS location and photo metadata, see Appendix 1.

Section III – AREAS OF CONCERN

No closing conference was held due to no personnel with Jerry Langley Oil Co., LLC being present during the inspection. There were no areas of concern during the inspection.

Section IV – FOLLOW UP

There were no areas of concern during the inspection, and a follow-up inspection is not required at this time.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 1 photo taken 05/09/2024.

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: Jerry Langley Oil Co, LLC – flowline release off an oil and gas lease road off All Gulf Rd (33.339567, -92.687617)		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: IMG_0030

Orientation: N

Date of Photo: 05/09/2024

Time of Photo: 1252

Latitude: 33.339614

Longitude: -92.687705

Photographer: Kerri McCabe

Description: Looking N, this photo showed the area of a flowline release from 03/14/2024 that had been remediated with sand.